



## Sch. XLV-Form No. 134

| Particulars                 | Details of actual measurement |    |    |    | Contents of area |
|-----------------------------|-------------------------------|----|----|----|------------------|
|                             | No.                           | L. | B. | D. |                  |
| Name of Work-               | Maintenance of Road           |    |    |    |                  |
|                             | from P.M.S. part Bihajar      |    |    |    |                  |
|                             | Jauharji Jha Ghar to          |    |    |    |                  |
|                             | Giraul Shewich dol tal        |    |    |    |                  |
| Agency -                    | Sri Shashi Kumar              |    |    |    |                  |
| Ag. No -                    | 35 / S.B.D. / 2019-20         |    |    |    |                  |
| Ag. Rate -                  | 0.18 / sq. ft.                |    |    |    |                  |
| Date of starting -          | 20.08.2019                    |    |    |    |                  |
| Actual Date of completion - | 22.09.2023                    |    |    |    |                  |
| ①                           | Restoration of Raiment        |    |    |    |                  |
|                             | Beams with soil               |    |    |    |                  |
|                             | do do                         |    |    |    |                  |

|    |         |       |       |                       |
|----|---------|-------|-------|-----------------------|
| 2x | 15.00x  | 0.9x  | 0.3 = | 8.1                   |
| 6x | 15.00x  | 1.00x | 0.3 = | 27.00                 |
| 6x | 10.00x  | 0.85x | 0.3 = | 15.300                |
| 9x | 29.00x  | 0.70x | 0.3 = | 34.81                 |
| 4x | 15.00x  | 0.80x | 0.3 = | 14.4                  |
| 1x | 5x      | 0.4x  | 0.3 = | 0.6                   |
|    | Net Qty |       |       | 120.21 m <sup>3</sup> |

|   |                     |        |       |                      |  |
|---|---------------------|--------|-------|----------------------|--|
| ② | Marking up of Beams |        |       |                      |  |
|   | Shoulder stripping  |        |       |                      |  |
|   | — do — do —         |        |       |                      |  |
|   | <del>27.50</del> 6x | 15.00x | 1.00x | 27.00 m <sup>3</sup> |  |
|   | 6x                  | 15.00x | 1.00x | 90.00 m <sup>3</sup> |  |
|   | 6x                  | 10.00x | 0.85x | 51.00 m <sup>3</sup> |  |

Continuation

# Abstract of cost

60

Sch. XLV-Form No. 134

| Particulars                                   | Details of actual measurement |    |    |     | Contents of area |
|-----------------------------------------------|-------------------------------|----|----|-----|------------------|
|                                               | No.                           | L. | B. | D.  |                  |
| ① Restoration of Rainwater                    |                               |    |    |     |                  |
| Berm with kerb                                |                               |    |    |     |                  |
| — do —                                        |                               |    |    |     |                  |
| TMB vide P (52) item ① = 120.4 m <sup>2</sup> |                               |    |    |     |                  |
| @ 380.58/m <sup>2</sup>                       |                               |    |    | Rs- | 45750.00         |
| ② Marking of of Berm                          |                               |    |    |     |                  |
| Shoulder stopping                             |                               |    |    |     |                  |
| — do —                                        |                               |    |    |     |                  |
| TMB vide P (52) item ② = 709.7 m <sup>2</sup> |                               |    |    |     |                  |
| @ 58.237/m <sup>2</sup>                       |                               |    |    | Rs- | 41482.00         |

|                                               |  |  |  |     |           |
|-----------------------------------------------|--|--|--|-----|-----------|
| ③ Repair of Pot holes                         |  |  |  |     |           |
| filled with 75mm                              |  |  |  |     |           |
| — do —                                        |  |  |  |     |           |
| TMB vide P (52) item ③ = 10.44 m <sup>2</sup> |  |  |  |     |           |
| @ 11251.80/m <sup>2</sup>                     |  |  |  | Rs- | 117469.20 |
| ④ Patch repair over                           |  |  |  |     |           |
| POT holes in top                              |  |  |  |     |           |
| set surface                                   |  |  |  |     |           |
| — do —                                        |  |  |  |     |           |
| TMB vide P (58) = 139.22 m <sup>2</sup>       |  |  |  |     |           |
| @ 291.291/m <sup>2</sup>                      |  |  |  | Rs- | 40640.20  |

Continuation

40640.20

| Particulars                        | Details of actual measurement |    |    |    | Contents of area |
|------------------------------------|-------------------------------|----|----|----|------------------|
|                                    | No.                           | L. | B. | D. |                  |
| (5) Maintenance of CD              |                               |    |    |    |                  |
| Work (M/P)                         |                               |    |    |    |                  |
| <del>do do</del>                   |                               |    |    |    |                  |
| TMD vide P (58) item (5) = 5 Mts   |                               |    |    |    |                  |
| (6) 1117.00 / each — 1 —           |                               |    |    |    | 5585.00          |
| (7) Maintenance of Road            |                               |    |    |    |                  |
| Grp/s — do do                      |                               |    |    |    |                  |
| TMD vide P (58) item (7) = 0.22 km |                               |    |    |    |                  |
| (8) 1074.25 / km — 1 —             |                               |    |    |    | 236.00           |
| (9) Maintenance of 200 m/s         |                               |    |    |    |                  |
| km stone — do do                   |                               |    |    |    |                  |
| TMD vide P (58) item 0.22 km       |                               |    |    |    |                  |
| (10) 653 = 52 / km — 1 —           |                               |    |    |    | 176.00           |
| (11) White washing of              |                               |    |    |    |                  |
| paper wall                         |                               |    |    |    |                  |
| <del>do do</del>                   |                               |    |    |    |                  |
| TMD vide P (59) item 10.30220 m    |                               |    |    |    |                  |
| (12) 105.00 / m — 1 —              |                               |    |    |    | 10836.00         |
| (13) Quantity of bricks of         |                               |    |    |    |                  |
| 200 x 80 x 100 mm                  |                               |    |    |    |                  |
| TMD vide P (58) item (13) = 2 Mts  |                               |    |    |    |                  |
| (14) 106.252 / km — 1 —            |                               |    |    |    | 320.20           |

Continuation

(14) 106.252 / km — 1 — 320.20

Continuation