

# 4 1/2 year maintenance

16

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Rakeha to Khamper.					
Agency: Sanyal Engrs. works					
Assno: 02/240/19/20					
Actual Date of completion: 24/6/20					
① Restoration of ceiling - Tse.					
					$2 \times 16 \times 30.00 \times 0.50 \times 0.20 = 96.00$
				Total =	96.00
				Unit =	76.95
② Maligning of beams / 20 mm plaster etc.					
					$2 \times 16 \times 30.00 \times 0.50 = 480.00$
				Total =	480.00
③ Repair of pot holes with 20 mm concrete					
					$1 \times 23.90 \times 3.75 \times 0.09 = 6.72$
				Total =	6.72
				Unit =	6.68
④ Patch repair over pot holes with 20 mm concrete carpet etc.					
					$1 \times 23.90 \times 3.75 = 89.63$
				Total =	89.63
				Unit =	89.06
⑤ Patch repair over bituminous surface with 20 mm concrete carpet etc.					
					$1 \times 8.50 \times 1.75 = 14.88$
					$1 \times 12.10 \times 2.50 = 30.25$
					$1 \times 11.71 \times 2.75 = 43.91$
				Total =	89.04

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B.F.	133992
(5) Pallet repair over bit wood, v. de l'ass. no. (5) 4008 (16)					
Qty = 89.04 m <sup>2</sup> @ 256.79/m <sup>2</sup>					22870
(6) Maint of CD wood (400)					
v. de l'ass. no. (6) 4008 (12)					
Qty = 50 m <sup>2</sup> @ 1109.67/m <sup>2</sup>					5548
(7) White washing of Pallet					
v. de l'ass. no. (7) 4008 (12)					
Qty = 105.00 m <sup>2</sup> @ 16.17/m <sup>2</sup>					1698
				Total =	164112
				(+) less 0.02% below (c) 33 =	
				Total =	164079

8800  
23/6/24  
AFC

MATERIAL STATEMENT

(1) Bit wood = 76.95 m <sup>3</sup>					
(2) Store chips = 5.54 m <sup>3</sup>					
(3) 1/2" 4008 emb-90 (16-10)				897.80 kg	
				8800	
				23/6/24	
				AFC	