

Sch. XLV-Form No. 134 61

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3rd year Maintenance					

Name of owner :- Maintenance of road from 6032 Paur Pandav than hore hore Dabu Tolarko Muslim Tolarko Hanjan Tolka under Munsif (SC)

Agency :- M/S Rameyam Thakur Co.

Regd No :- 1133D/1857

Date of Agreement :- 28/04/2020

End Date :- 30/09/2020

Work done

① P/R restoration of embankments

$$\begin{aligned} & \text{Side } 1: 1.5 \times 1.25 \times 0.30 \\ & = 1.4375 \text{ m}^3 \end{aligned}$$

$$\begin{aligned} & \text{Side 2: } 1.100 \times 1.25 \times 0.300 \\ & = 1.55 \cdot 93 \text{ m}^3 \end{aligned}$$

$$\begin{aligned} & \text{Total: } 2 \times 1.4375 + 2 \times 1.55 \cdot 93 \\ & = 4.173 \text{ m}^3 \end{aligned}$$

$$\therefore 30.4173 \text{ m}^3$$

② P/R excess of

Soil

513

$$122 \text{ M-10 } 0.513 \times 9.100 \times 1.25 = 6.40 \cdot 50$$

$$255 \text{ M-10 } 2.12 \times 1.455 \times 1.25 = 1.05188 \text{ m}^3$$

$$\therefore 16.92 \cdot 28$$

Continuation

m/s

Sch. XIV-Form No. 10.

B.I. 288614.