

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/24th Year maintenance					
Name of place					Maintenance of
From 2016 to Ahmad Pur					
Yadav tola					
Aug - Saffender Kumar Singh					
And no - 488331 / 2018-19					
Date of Completion - 6.1.2020					
Date of work - 10.1.2024					
1) Restoration of fountain cuts					
with all completions					
10 x 15m x 1m x 0.30 = 45-cu ³					
16 x 15m x 0.75 x 0.30 = 54..					
8 x 15m x 0.60 x 0.30 = 21.30					
					120.30cu ³
2. making up of Berms					
Shifting with all					
10 x 15m x 2 x 0.90 = 270-cu ²					
10 x 15m x 2 x 0.75 = 360..					
6 x 15m x 2 x 0.60 = 108					
					738-cu ²
					Sum 733.92cu ²
3. Repair of Pot holes.					
Filled with Bm with all					
6 x 3m x 2m x 0.075 = 2.70cu ³					
7 x 2m x 1.5m x 0.075 = 1.575					
4 x 1m x 1m x 0.075 = 0.30					
					4.575cu ³
					Sum 4.46cu ³

[illegible]