

N/W - Maint. of Road from Darigaon
PWD Path Kali Sthan Mahadaili
Basti: hote hue Durgawati Jalgaon to
Bhakhara - 2.100km
Agency - Sharda Bhawani Infra. PVT. LTD.
Ag. No - 27/ SBD/2019-20
Date of start - 19/09/2019
Actual date of comp - 28/05/2021

- ① Restoration of Rainwater - d -
 Bty vide TMS R No - (72)
 I. No. ① 148.792 m³ @ 380.58 = 56627.00
- ② Making up of Bore/shoulder
 striping d - d

Continuation

100

Particulars	Details of actual measurement			Contents of area
	No.	L	B	
Qty vide TM B P. No. (73)				
I. No. (2) 708.584 m ² @ 57.54 =				40772 = ∞
③ Repair of Pot. holes filled 75mm BM d-6				
Qty vide TM B P. No. (73)				
I. No. (3) 9.75 m ² @ 11989.38 =				116896 = ∞
④ Patch repair of Crs. bit. in the 20mm premix carpet d-				
Qty vide TM B P. No. (73)				
I. No. (4) 129.172 m ² @ 322.31 =				41633 = ∞
⑤ Patch repair of Crs. bit. in bituminous 20mm premix				
Qty vide TM B P. No. (73)				
I. No. (5) 129.12 m ² @ 339.67 =				43858 = ∞

⑥ Maint. of HPC				
Qty vide TM B P. No. (74)				
I. No. (6) 9. No. @ 1117.0 =				10053 = ∞
⑦ Maint. of Road Signs				
Qty vide TM B P. No. (74)				
I. No. (7) 0.32 km @ 1074.51 =				338 = ∞
⑧ Maint. of 200m km stone				
Qty vide TM B P. No. (74)				
I. No. (8) 0.38 km @ 339.67 =				247 = ∞
⑨ Cutting of branches of tree shrubs d-				
Qty vide TM B P. No. (74)				
I. No. (9) 106.52 =				533 = ∞
⑩ Cutting of shrubs from road way				

Particulars	Details of actual measurement				Contents of area
	No.	L	B	D	
Qty vide TM B P No. (74)					
I. No. (i) 21. No. @ 6.54 =					137.00
(ii) Cutting of shanks from					
no					
(11) white washing on					
perceped wall do do					
Qty vide TM B P No. (74)					
I. No. (i) 189.0 m ² @ 16.59 =					3136.00
Total					314225.00
Less 10% Balance RS (-) =					31423.00
					282803.00
					282807.00

Material Statement

Soil = 335.171 m³100mm stone chips 5.062 m³Stone dust - 0.103 m³

SS = 109.79 kg

RS = 71.9 kg

V₀₋₁₀ = 490.65 kg

Continuation