

Baggi hat to Khorsan Basti via Korian

Baksh to/g.

MMBSY General

Schedule XLV-Form No. 134

Maintenance

P-15

KISHANWANJ-1 DIVISION

BALHADDIKHANI SUB-DIVISION

Measurement Book

1312

Cauvisee Perwez Wazidi

5th year Maintenance Bill

25

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/10:- Maintenance of Road from Ganga hat to Kharsan basti via Karam Jaksq Colg in Bahad Agency Molele					
Agency - Quaiser perwar Wazoli					
Aggrn - 30/11/16/2014-15					
Dt. of start - 17/2/16					
Dt. of comp - 10/3/17					

1) Restoration of Kharab

1 X 30.0 X 2.2 X 0.3 =	19.80
2 X 30.0 X 2.25 X 0.3 =	40.50
1 X 30.0 X 2.0 X 0.3 =	18.0
1 X 30.0 X 2.20 X 0.3 =	19.80
1 X 30.0 X 2.25 X 0.3 =	20.25
1 X 12.0 X 2.00 X 0.3 =	8.28
	Qty = 126.63
	m ³

2) Maintenance of earthen Shoulder

1 X 30.0 X 1.25 =	37.50
3 X 30.0 X 1.14 =	102.60
4 X 30.0 X 1.25 =	150.0
2 X 30.0 X 1.30 =	78.0

Continuation

Continuation