

कार्यालय
कार्यपालक अभियंता, ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय, समस्तीपुर

पत्रांक 1697 दलसिंहसराय / दिनांक 16/12/2024

प्रेषक, कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, दलसिंहसराय

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी,
सचिव -सह- प्राधिकृत पदाधिकारी, बिहार
ग्रामीण पथ विकास एजेंसी पटना।
विषय- New Maintenance Policy 2018 योजनान्तर्गत पथ में आवंटन उपलब्ध कराने के
संबंध में।

महाशय,

उपरोक्त विषय के संबंध में कहना है कि New Maintenance Policy 2018 योजनान्तर्गत चल रहे पथ के निर्माणधीन कार्य के विरुद्ध चल रहे योजनाओं का भुगतान की आवश्यकता है। अधियाचना का निर्माण कार्य विशिष्टियों के अनुरूप है तथा कार्य संतोषप्रद है।

अतः अनुरोध है कि अधियाचना पत्र के आधार पर आवंटन उपलब्ध कराने की कृपा की जाय।

अनु- 1) अधियाचना प्रपत्र।

2) 19ए फॉर्म।

विश्वासभाजन

16/12/24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

FROM GFR-19-A

(See Govt. of India's decision(i) below rule 150)
Form of Utilisation Certificate upto Dec- 2024

New Maintenance Policy 2018(MR New)

PIU:- RWD Works Division Dalsinghsarai

Sl No	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lakh)	Amount Received (in Lakh)	Particulars
1	2	3	4	5
1	New Maintenance Policy 2018 (MR New)	11758.26882	11758.26882	Certified that out of Rs-11758.26882 Lakh Received till date in favour of Executive Engineer, RWD Works Division Dalsinghsarai a Sum of Rs-11596.24167 Lakh has been utilized for the New Maintenance Policy 2018 (MR New) Scheme as given in the margine for which it was Sanctioned and that the Balance of Rs-162.02715 Lakh remaining unutilized at the end of period under the time of completion
		11758.26882	11758.26882	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was

Kind of Checks Exercised:-

- (i) Workers have been supervised by Executive Engineer/ Superintending Engineer
- (ii) Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer
- (iii) Construction materials have been tested
- (iv) Measurments have been recorded in the MB's and test check conducted by the
- (v) All other codal formalities have overserved

3. Physical Progress Achieved

- (i) Construction of Road Works
- (ii) Construction of CD Works

DAO 16/12/2024
Rural Works Department,
Works Division Dalsinghsarai

16/12/24
Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

Rural Works Department, Works Division Dalsinghsarai
Requisition Format for Scheme Head - MR (3054) Under Bihar Rural Road maintenance Policy 2018
(Initial Rectification and Surface Renewal)

Name of Division : PU(Dalsinghsarai)

Sl. No	Package no.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (1 Lac)	up to date expenditure as per MIS (in Lac)	Requisition Against work done (in lac)	Remarks
					Length (in Km)	Amount (in Lac)	Initial Rectification with Surface Renewal (in lac)	5 years Routine Maintenance (in lac)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
RM/SA/DAL/24/0003																		
		Banberiya to Dalsinghsarai	32010408105	6120/04.12.23	6.70	408.03	317.02716	48.34366	31MBD/24-25 02.08.2024	01.05.2025	16.12.24	3165	25mm	5.10%	285.32444	285.32444	31.58167	
2		L039 To Harijan Tola	32010412002	6120/04.12.23	1.25	70.4	54.34792	10.07308	31MBD/24-25 02.08.2024	01.05.2025	16.12.24	3198	25mm	5.10%	0.00000	0.00000	54.27910	
3		L054-T03 to Belandi Dih (VR54)	32010402076	6120/04.12.23	1.52	88.66	67.10629	11.02762	33MBD/24-25 02.08.2024	01.05.2025	-	3517	25mm	5.10%	0.00000	0.00000	60.39566	
TOTAL					6.700	408.030	317.027								285.32444	285.32444	146.25643	

1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.

2 Up-to date Physical Progress has been uploaded in MIS


Divisional Account Officer
Rural Works Department,
Works Division Dalsinghsarai

19/12/24


16.12.24
Executive Engineer
Rural Works Department,
Works Division Dalsinghsarai

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, दलसिंहसराय


क्र०सं०	प्रतिवेदन	अभ्युक्ति
शर्त		
1	मापी पुस्त पर इस आशय का प्रमाण पत्र दर्ज है कि कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है।	L054-T03 to Belsandi Dih (VR54) का निर्माण कार्य गुणवत्ता पूर्ण कराया गया है एवं विशिष्टियों के अनुरूप है।
2	कराये गये कार्यों के सभी अवयवों के अवयववार 100 प्रतिशत कार्य का दर्ज मापी का सत्यापन कनीय अभियंता, कम से कम 50 प्रतिशत मापी का सत्यापन सहायक अभियंता एवं कम से कम 10 प्रतिशत मापी का सत्यापन कार्यपालक अभियंता द्वारा किये जाने का प्रमाण - पत्र को विभागीय MIS पर अपलोड जाय।	L054-T03 to Belsandi Dih (VR54) का कराये गये कार्यों के सभी अवयवों के अवयववार मापी का सत्यापन कनीय अभियंता, सहायक अभियंता एवं कार्यपालक अभियंता द्वारा किया गया है।


16.12.24

कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, विभूतिपुर


16.12.24

सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, विभूतिपुर


16.12.24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, दलसिंहसराय

42251

Name of Customer: Maa Shanti Infra Developers Private Limited, Machine no: 19192, Road: L054-T03 to Belisandi Dih (FRS4), Date: 16-12-24, Section No: 03, Equation: $Y=0.893X+355$

0.19205

-3.841

100

1050

Distance*1000 m

2000

gm hsc
16.12.24
9.6

16.12.24

of the work: L054-T03 to Belsandi Dih (VRS4)

Date	Time	Test No	Distance (meter)	Total Distance (meter)	BU MP (cm)	Speed (Km/Hr)	UI (mm/Km)	Corrected UI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction	Remarks
16-12-2024	16:21:41	3	100	100	22.0 cm	12.8 Km/Hr	2200.0 mm/Kr	2310.8	3.191	Good	25.74315	N	85.952985	E	Normal
16-12-2024	16:22:04	3	100	200	26.0 cm	16.2 Km/Hr	2600.0 mm/Kr	2666.4	3.626	Good	25.743537	N	85.952433	E	Normal
16-12-2024	16:22:34	3	100	300	27.0 cm	11.1 Km/Hr	2700.0 mm/Kr	2755.3	3.734	Good	25.743905	N	85.951838	E	Normal
16-12-2024	16:22:51	3	100	400	25.0 cm	21.8 Km/Hr	2500.0 mm/Kr	2577.5	3.518	Good	25.744418	N	85.951303	E	Normal
16-12-2024	16:23:07	3	100	500	26.0 cm	22.2 Km/Hr	2600.0 mm/Kr	2666.4	3.626	Good	25.743949	N	85.950753	E	Normal
16-12-2024	16:23:31	3	100	600	25.0 cm	15.3 Km/Hr	2500.0 mm/Kr	2577.5	3.518	Good	25.743323	N	85.949355	E	Normal
16-12-2024	16:23:51	3	100	700	28.0 cm	14.4 Km/Hr	2800.0 mm/Kr	2844.2	3.841	Good	25.743225	N	85.948781	E	Normal
16-12-2024	16:24:11	3	100	800	26.0 cm	15.7 Km/Hr	2600.0 mm/Kr	2666.4	3.626	Good	25.743287	N	85.948206	E	Normal
16-12-2024	16:24:31	3	100	900	25.0 cm	16.2 Km/Hr	2500.0 mm/Kr	2577.5	3.518	Good	25.742941	N	85.947568	E	Normal
16-12-2024	16:24:51	3	100	1000	23.0 cm	15.1 Km/Hr	2300.0 mm/Kr	2399.7	3.301	Good	25.742374	N	85.947175	E	Normal
16-12-2024	16:25:21	3	100	1100	25.0 cm	14.2 Km/Hr	2500.0 mm/Kr	2577.5	3.518	Good	25.742026	N	85.946395	E	Normal
16-12-2024	16:25:41	3	100	1200	24.0 cm	15.4 Km/Hr	2400.0 mm/Kr	2488.6	3.41	Good	25.741633	N	85.947396	E	Normal
16-12-2024	16:26:10	3	100	1300	26.0 cm	15.5 Km/Hr	2600.0 mm/Kr	2666.4	3.626	Good	25.741154	N	85.948444	E	Normal
16-12-2024	16:26:21	3	100	1400	27.0 cm	14.7 Km/Hr	2700.0 mm/Kr	2755.3	3.734	Good	25.740651	N	85.948768	E	Normal
16-12-2024	16:26:55	3	100	1500	24.0 cm	14.3 Km/Hr	2400.0 mm/Kr	2488.6	3.41	Good	25.739957	N	85.948754	E	Normal
16-12-2024	16:27:15	3	100	1600	21.0 cm	14.3 Km/Hr	2100.0 mm/Kr	2221.9	3.081	Good	25.739014	N	85.950192	E	Normal

IRI Value 3517
Machine ID 19192

[Signature]
16.12.24
25

[Signature]
16/12/24
AR

[Signature]
16.12.24