

3rd year maintenance Bill

48

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work: Maintenance of Road from					
71H30 Baha to Baha Toham Village					
Mahadit tola.					
Agency-	Jai maa Construction				
App. No -	86-680/2018-19				
Actual date of completion-	20/02/2020				

MEASUREMENT

① Restoration of rain cuts

.....20.....20.....91					
48x	0.60x	1.20x	0.30	10.368m ³	
36x	0.75x	1.20x	0.30	9.720m ³	
32x	0.90x	1.20x	0.30	10.368m ³	
28x	1.15x	1.20x	0.30	11.592m ³	
22x	1.45x	1.10x	0.30	10.527m ³	
16x	1.90x	1.10x	0.30	10.032m ³	
12x	2.25x	1.10x	0.30	8.910m ³	
8x	2.65x	1.15x	0.30	7.314m ³	
6x	2.90x	1.00x	0.30	5.220m ³	
8x	3.15x	1.00x	0.30	7.560m ³	
6x	4.85x	1.15x	0.30	10.040m ³	
2x	7.45x	1.20x	0.30	5.364m ³	
.....				107.015m	

② Maintenance of gutter shoulder

.....20.....20.....91					
2x	6x	6.40x	1.20	92.16m ²	
2x	4x	8.60x	1.20	82.56m ²	
2x	6x	7.35x	1.10	93.02m ²	
2x	4x	9.60x	1.10	84.48m ²	
Continuation				356.22m ²	

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	8.1				356.22 m ²
	2x	6x	11.75 x 1.10		155.10 m ²
	2x	4x	9.45 x 1.10		83.16 m ²
					594.48 m ²
③ Repair of Art holes with B.H.					
.....20.....20.....E ₁					
	32x	0.60 x 0.60 x 0.075			0.864 m ³
	28x	0.75 x 0.60 x 0.075			0.945 m ³
	18x	0.90 x 0.75 x 0.075			0.911 m ³
	14x	0.90 x 0.90 x 0.075			0.851 m ³
	8x	1.45 x 1.15 x 0.075			1.001 m ³
	4x	2.15 x 1.75 x 0.075			0.806 m ³
	2x	2.75 x 2.30 x 0.075			0.949 m ³
					6.327 m ³
④ Patch repair over Art. holes					
.....20.....20.....E ₂					
	32x	0.60 x 0.60			11.52 m ²
	28x	0.75 x 0.60			12.60 m ²
	18x	0.90 x 0.75			12.15 m ²
	14x	0.90 x 0.90			11.34 m ²
	8x	1.45 x 1.15			13.34 m ²
	4x	2.15 x 1.75			10.75 m ²
	2x	2.75 x 2.30			12.65 m ²
					84.35 m ²
⑤ Maintenance of H.P. Culvert					
.....20.....20.....E ₁					
		3.00 m			3.00 Hrs.
⑥ Cutting of branches of trees					
.....20.....20.....E ₁					
					12.00 Hrs.

Continuation

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	B.P.				Rs 14329.20
④ Patch repair over Asf h/100					
.....20.....20.....				EL	
84.35 m ²	VTMBP-49				
	@ 1/1256.45/m ²			Rs	21635.00
⑤ Maintenance of H.P. Culvert					
.....20.....20.....				EL	
5.00 Nos.	VTMBP-45				
	@ 1/1101.637/M.			Rs	3329.00
⑥ Cutting of branches of trees					
.....20.....20.....				EL	
3.00 Nos.	VTMBP-49				
	@ 1/115.938/m ²			Rs	348.00
⑦ Cutting of shrubs from roadway					
⑧ Trimming of grass & weeds					
.....20.....20.....				EL	
30.00 m ²	VTMBP-50				
	@ 1/2.141/m ²			Rs	64.00
⑨ White washing of Airport walls					
.....20.....20.....				EL	
61.92 m ²	VTMBP-50				
	@ 1/16.36/m ²			Rs	1018.00
				Rs	17016.200
Loss 10% As per				Rs	17016.200
				Rs	153145.00
C/S					
M. M. M. M.					
(A-E)					
Continuation					J.C

Scanned with CamScanner