

M.B. NO - 47020-21

Warrant Karmar from

Maint

Measurement Book

Schedule XLY-Form No. 134

Damohat Hapur Hapur to be DIVISION Aleks
To Bathanya To be

~~flor silk~~ SUB-DIVISION

Mortimer

MUNDA KUMAR SENGH

3rd Year Maintenance

16

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work-	Maintenance of road				
from	Dambhri Hapur Harijan				
To	Bathniya Talga (nnnsy)				
Agency-	Sri Munna Kumar Singh				
Agreement No-	455BD/2019-20				
Actual date of completion-	06/07/2020				
3rd year maintenance?	07/07/2022 to				
Period	06/07/2023				

① Restoration of Rain cuts

1 X	8.10	X	1.20	X	0.30 =	2.9211
2 X	9.50	X	1.10	X	0.25 =	5.2211
3 X	10.10	X	1.15	X	0.25 =	8.6211
2 X	7.10	X	0.90	X	0.30 =	3.8311
2 X	8.10	X	1.20	X	0.30 =	5.7611
2 X	11.10	X	1.25	X	0.30 =	8.2511
2 X	10.10	X	1.20	X	0.30 =	7.2011
3 X	8.50	X	1.15	X	0.30 =	8.8011
3 X	7.40	X	1.15	X	0.25 =	6.0311
4 X	9.10	X	1.20	X	0.30 =	12.9611
4 X	8.15	X	1.20	X	0.25 =	9.7811
						79.3711

② Maintenance of earthen shoulder

3	X	8.10	X	1.15 =	27.9411
5	X	7.10	X	1.15 =	40.2511
4	X	9.50	X	1.25 =	47.5011
5	X	15.10	X	1.25 =	93.7511
4	X	22.10	X	1.20 =	105.6011
					315.0411

Continuation

Scanned by CamScanner

Scanned by CamScanner