

M.B. NO - 47020-21

Memorandum Form

Maint

Measurement Book

Schedule XLY-Form No. 134

Dombhri Hengur Hengur to be DIVISION Ades
To Bathanya To be

~~Sub Division~~ / Sub Division SUB-DIVISION

Mortimer

MUNDA KUMAR SENGH

4th Year Maintenance

22

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Damohriti Harpur Harijan Tola to Bathniya Tola under MWSY					
Agency- Sri Manna Kumar Singh					
Agreement No- 455BD/2019-20					
Actual date of completion- 06/07/2020					
4 th Year Maintenance? 07/07/2025 to Period } 06/07/2024					
① Restoration of Raiment					
1 X	6.25	X	1.10	X	0.25 = 1.7211
2 X	10.50	X	1.20	X	0.25 = 6.3011
1 X	7.50	X	1.20	X	0.25 = 2.2511
2 X	8.40	X	1.25	X	0.25 = 5.1011
3 X	10.40	X	1.20	X	0.25 = 9.1011
2 X	5.50	X	1.20	X	0.25 = 3.3011
2 X	7.10	X	1.10	X	0.30 = 4.6211
2 X	8.40	X	1.20	X	0.25 = 4.8011
2 X	11.50	X	1.25	X	0.25 = 7.1911
2 X	9.50	X	1.25	X	0.25 = 5.9411
1 X	7.65	X	1.20	X	0.25 = 2.2911
2 X	6.40	X	1.25	X	0.30 = 4.5011
2 X	10.40	X	1.25	X	0.30 = 3.7511
1 X	7.10	X	1.15	X	0.25 = 2.0411
1 X	12.40	X	1.20	X	0.30 = 4.3211
2 X	7.40	X	1.10	X	0.25 = 3.8511
3 X	9.40	X	1.20	X	0.30 = 9.2711
2 X	11.40	X	1.25	X	0.30 = 8.2511
1 X	7.75	X	1.20	X	0.25 = 2.3211
					90.7111

Continuation

Scanned by CamScanner

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
c R 6.54/each - R					92=00
(7) Trimming of grass					
Q-VTNB/25(6) = 564.001					
c R 2.18/11 - R					123020
(8) White washing on parapet					
Q-VTNB/24(6) = 20.6411					
c R - 16.65/11 - R					344=00
(9) Maintenance of road sign					
Q-VTNB/25(7) = 1.120 Km					
c R 1074.511/Km R					120320
(10) Maintenance of 200m stone					
Q-VTNB/25(8) = 0.202 Km					
c R - 729=071/Km R					147=00
				R - 1,41,519=00	
Less 0.05% below ->					71=00
				R - 1,41,448=00	
				0111/129 AG	0111/24 J.E