

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1st Repair Maintenance:					
N/W:- Maintenance of Road					
From Palakpurhigri Garkwa					
Path To Mangari Bashi					
Khap Tola.					
Agency:- Smt. Neta Karonari					
Agreement No:- SBT 54/2021-22					
Date of work order- 30.08.21					
Date of entry - 29/11/21					
① Restoration of Panels					
do do					
5x8.50x0.90x0.302					11.48
3x5.20x0.95x0.302					4.45
7x9.10x1.10x0.302					21.02
4x9.50x0.90x0.302					10.26
6x6.00x1.00x0.302					10.80
8x8.00x1.00x0.302					19.20
					77.21m ²
② Maintenance of culvert					
do do					
7x11.00x0.902					69.30
9x9.00x1.002					81.00
6x9.50x1.002					57.00
7x6.50x1.102					50.05
9x9.50x1.102					94.05

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
		8x	9.00x	1.10	272.90
					6430.60
(3) Mount of up connect					
do do					
		1x	1		1 NS
(4) Mount of Road sign					
do do					
		1x	0.93	km	= 0.93 km
(5) Mount of 2004 sign					
do do					
		1x	0.111	km	= 0.111 km
(6) Entry of Branching					
do do					
				5 NO	5 NO
(11)					
29/11/24					
ABSTRACT OF COST					
(1) Restoration of Rumeny					
do do					
77.4 m ² at 11000/-					1010.10
@ 388.11/m ²					29966.10
(2) Mount of entire work					
do do					
430.60 m ² at 11000/-					1100.00
@ 55.05/m ²					23963.10

Continuation

Continuation