

33355
Schedule XLV-Form No. 134

P/N:- Sathbitta Pmosy Road to Masjid Tola

R.M.D WORKS

DIVISION

KISHANGANGY-I

R.M.D WORKS

SUB-DIVISION

KOCHADHAMAN

3208

Measurement Book

Assamchi- MD Gaznafers Rabgarni,

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>1st year maintenance bill</u>					
Name of work- maintenance of Road					
from Satbhitta Pmvisy Road to					
Masjid Tola under Mmvisy (ST)					
Agency - Md. Ghafor Rabbani					
Agreement No - 83/Mmvisy/SGD/2020-21					
Date of commencement - 15-06-2020					
Actual date of completion - 20-03-2022					
(1) Restoration of Rain					
cuts with soil - all complete					
$5 \times 2.80 \times 0.75 \times 0.300 = 3.15m^3$					
$12 \times 1.90 \times 0.80 \times 0.300 = 5.47m^3$					
$9 \times 1.50 \times 0.60 \times 0.300 = 2.43m^3$					
<u>11.05m³</u>					
$11.05m^3 @ RS 379 = 59/m^3$ RS 4194=00					
(2) Stripping Excess soil					
from the shoulders - -					
all complete					
$18 \times 3.50 \times 0.90 = 56.70m^2$					
$25 \times 2.90 \times 0.80 = 58.00m^2$					
$43 \times 1.80 \times 0.70 = 66.48m^2$					
<u>25</u>					
<u>31.50m²</u>					
<u>175.18m²</u>					
<u>146.20m²</u>					
$146.20m^2 @ RS 56 = 81/m^2$ RS 9952=00					
<u>8306=00</u>					
(3) patch repairs with 20mm					
mix seal surfacing - -					
all complete					
<u>12</u>					
$23 \times 0.90 \times 0.50 = 10.35m^2$					
<u>5.40</u>					
$10.35m^2 @ RS 203 = 69/m^2$ RS 1100=00					
<u>2408=00</u>					

Continuation C.O RS 16254=00
13600=00

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
				B/R S	16254=00
(4) maintenance of Hume pipe culvert -- all complete					13600=00
7.0 NO @ RS 1144 = 42 / each RS					1144=00
(5) cutting of branches of tree & shrubs -- all complete					
7.0 NOS @ RS 110 = 12 / each RS					110=00 220=00
				RS	14854=00
Add GST 12.0 %				+ RS	1782=00
Add L.C. 1.0 %				+ RS	149=00
				RS	16785=00
less 0.21 % below as per aggrs					35=00
				RS	16750=00
W/ signed					
25.03.2023				Jy	
JE				06.07.23	AE

Sch. XLV — Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>2nd year maintenance bill</u>					
<u>Name of work — Maintenance of Road</u>					
<u>from Sathbitta panchayat Road to</u>					
<u>Masjid Tola under MMWSY (ST)</u>					
<u>Agency — Md. Giaznafar Rabbani</u>					
<u>Agreement No — 83/MMWSY/SBD/2020-21</u>					
<u>Date of Commencement — 15-06-2020</u>					
<u>Actual Date of Completion — 20-03-2022</u>					
<u>1) Restoration of Rain</u>					
<u>Cuts with Soil — — —</u>					
<u>all complete</u>					
$12 \times 1.90 \times 0.80 \times 0.300 = 5.47m^3$					
$9 \times 1.50 \times 0.60 \times 0.300 = 2.43m^3$					
$5 \times 2.20 \times 0.75 \times 0.300 = 3.15m^3$					
$3 \times 1.30 \times 0.65 \times 0.300 = 1.05m^3$					
$13 \times 0.80 \times 0.50 \times 0.300 = 1.56m^3$					
$13.37m^3$					
$13.37m^3 @ Rs 379 = 59/m^3 Rs 5075=00$					
<u>2) Stripping Excess Soil</u>					
<u>from the shoulders — — —</u>					
<u>all complete</u>					
$25 \times 1.80 \times 0.80 = 36.0m^2$					
$42 \times 2.10 \times 0.90 = 79.38m^2$					
$28 \times 2.50 \times 0.85 = 59.50m^2$					
$174.88m^2$					
$174.88m^2 @ Rs 56 = 81/m^2 Rs 9935=00$					
$C.O Rs 15010=00$					

Sch. XLV—Form No. 134					
Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			B/Rs		15010=00
③ patch repair with 20mm mix seal surfacing -- -- all complete.					
22x0.70 x 0.50 = 7.70 m ²					
7 x 0.90 x 0.40 = 2.52 m ²					
			10.22 m ²		
10.22 m ² @ Rs 203 = 69/m ² RS					2082=00
④ maintenance of Hume pipe culvert - all complete					
1.0 NO @ Rs 1144 = 42/each RS					1144=00
⑤ cutting of branches of trees and shrubs -- all complete					
2.0 NOS @ Rs 110 = 12/each RS					220=00
				RS	18456=00
Add GST 12.0%				+ RS	2215=00
Add L.C. 1.0%				+ RS	185=00
				RS	20856=00
less 0.2% below 95 per cent RS					44=00
				RS	20812=00
w/ gear					
25.03.2024					
J5					
					26.03.24 AJ