

5th year maint. 17.12

23

Sch. XIV Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L	B	D	
Name of work - Maint. of Road					
From Chaudhigani - Tulua Road					
To from more under 17.12.24					
NDIS					
Agency - Sathish Kumar					
Agreement dt. - 01.10.23 to 31.10.24					
W/O Completion - 31.10.24					
Maint. Period - 01.10.23 to 31.10.24					

Accepted

Priform

17.12.24

Second Entry

① Restoration of Pucca/Berms

scil. masonry etc.

9 X 2.25 X 0.30 X 0.30 = 5.47 m ³	
7 X 3.0 X 1.0 X 0.25 = 5.25 "	
12 X 2.75 X 1.10 X 0.25 = 9.08 "	
9 X 3.25 X 1.10 X 0.30 = 9.65 "	
8 X 3.0 X 1.15 X 0.30 = 8.28 "	
5 X 2.50 X 1.00 X 0.30 = 8.10 "	
6 X 2.50 X 1.00 X 0.25 = 3.75 "	
7 X 2.75 X 0.75 X 0.30 = 4.33 "	
8 X 3.00 X 1.00 X 0.20 = 6.14 "	
9 X 2.00 X 0.75 X 0.25 = 3.38 "	
	63.43 m ³

(Continuation)

Sch. XLV. Form No. 134

Particulars	Details of actual measurement				Contents or area
	No.	L.	B.	D.	
Abstract of vol of earth year mnt. 17.11					
① Restoration of pavement Berms with soil masonry					
55.63 m ³ vide TMB P.No (23)					
@ 332.04/m ³					R. 18661.0
② Making up of Berms/ shoulder, stripping excess soil etc.					
518.80 m ² vide TMB P.No (24)					
@ R. 53.30/m ²					R. 27652.0
③ Repair of pot holes filled with 14.7 cm concrete					
6.41 m ³ vide TMB P.No (24)					
@ 374.31/m ³					R. 2393.0
④ Patch repair on already filled pot holes with 75 mm 13M					
85.78 m ² vide TMB P.No (25)					
@ R. 244.79/m ²					R. 20998.0
⑤ Repair to pot holes and removal of loose materials					
82.03 m ² vide TMB P.No (25)					
@ R. 263.37/m ²					R. 21604.0
⑥ Maint of CD works 6 Nos. vide TMB P.No (26)					
@ R. 1131.64					R. 6730.0

(Continuation)

(Continuation)

Scanned with CamScanner