

2nd year maintenance

84

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: chakra					
chouk maricha Road to					
Lachmipar					
2. Name of Agency: pramod Kumar					
3. Agreement No: 55/SRD/201920					
4. Actual dt. of completion: 15-08-2022					
- measurement as below -					
① Restoration of drain cuts					
With soil surface					
	5	30.0	1.0	0.30	= 45.0
	5	30.0	0.90	0.30	= 31.50
	1	20.60	0.80	0.28	= 4.614
	1	18.90	0.70	0.30	= 3.969
	1	20.62	0.80	0.28	= 4.618
	1	2.50	0.70	0.30	= 0.525
	1	4.50	0.72	0.32	= 1.036
					Qty = 91.262 m ³
					Savg Qty = 91.13 m ³
② maintenance of earthen					
shoulder durbur					
	1	20.50	0.6		^{12.30} = 20.50
	5	30.0	0.90		= 135.0
	6	30.0	0.85		= 153.0
	2	30.0	0.72		= 43.20
	6	30.0	0.75		= 135.0
	2	20.60	0.60		^{24.72} = 27.08
	1	6.0	0.50		= 3.0
	1	1.8	0.20		= 0.20
					C.O. Qty = 506.42 m ³
					Savg Qty = 506.25 m ³
					P.T.O.

Continuation?