

2nd year maintenance

41

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Point of roof from TDS to Modhapur Kapur Talga.					
Agency - Murshid Ali.					
Agreement No. - 40389/20-21					
Date of start - 11.06.2020					
Actual completion - 10.06.2021					
Record Entry					
(1) Restoration of rain water with soil - do -					
8 x 3.80 x 0.90 x 0.30 =					6.16
8 x 2.90 x 0.75 x 0.30 =					6.61
9 x 2.80 x 0.80 x 0.30 =					6.05
7 x 4.90 x 0.75 x 0.30 =					6.93
6 x 5.80 x 0.65 x 0.30 =					6.79
7 x 4.90 x 0.85 x 0.30 =					8.75
8 x 4.70 x 0.70 x 0.30 =					7.90
6 x 4.80 x 0.80 x 0.30 =					6.91
12 x 3.40 x 0.65 x 0.30 =					7.96
8 x 4.80 x 0.75 x 0.30 =					8.64
16 x 2.90 x 1.00 x 0.30 =					13.92
14 x 2.25 x 1.05 x 0.30 =					12.13
					Total = 98.85

Continuation

[illegible]

Continuation