

Allocation Rs -

II Year maintenance

56

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

Maintenance maintenance at 200
from dauter Pur Saur to Saur Road
meters

Survey - Rg Kmr at Rector Po.
Rector Saur

Survey no. - 01/ SBO/2021-22

Actual date of survey - 25/4/22

① Restoration of drain cuts -

2x 9.00 x 1.00 x 0.30 = 5.40 m

3x 10.00 x 0.90 x 0.30 = 9.00 m

4x 6.00 x 1.00 x 0.30 = 7.20 m

4x 8.00 x 1.00 x 0.30 = 9.60 m

2x 9.00 x 1.50 x 0.30 = 8.10 m

2x 6.00 x 1.00 x 0.30 = 3.60 m

① 4x 7.00 x 1.20 x 0.30 = 10.80 m

= 52.90 m

Limit 9.82 = 49.82 m

② Maintenance at earthwork

Shoulders -

① 4x 12.00 x 0.90 = 43.20 m

4x 11.00 x 0.90 = 39.60 m

4x 13.00 x 0.90 = 46.80 m

2x 18.00 x 1.00 = 36.00 m

② 4x 10.00 x 1.00 = 40.00 m

8x 12.00 x 0.80 = 76.80 m

282.40 m

Continuation 276.75 m

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
			6.11		57619.0
② Center for Borens					
or trees					
Q.S. - 3000 vide					
Plan No. 57					
② 6.73/NO. 11 - 69.0					
③ Timber gross way					
Q.S. - 6.71 x 8.42 vide					
Plan No. 57					
② 2.24/11 - 1550					
④ Maintenance on					
already Plotted					
Q.S. - 6.71 x 8.42 vide					
Plan No. 57					
② 6.55/11 - 28855.0					
					86093.2
Add 12.11.11 - 10331.0					
Add 11.11.11 Cuts - 860.0					
As per Assump. 11 - 97284.0					
Less 21.11.11 below					20517.0
					76767.0
24/10/11					
Material Stamp -					
Q.S. - 49.82 m ²					

Continuation