

3rd year maintenance

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work -					maint of roof from
Mahua Mukhya path to Baginapur					
Mahadoli lot					
Agency -					Abhay Kumar Thakur
Agreement no. -					49130/90-21
Date of work order -					10.08.2020
Actual completion -					09.08.2021

Record Entry

① Restoration of roof
was 1.25 sq ft

3 x 4.60 x 0.80 x 0.30 = 5.31

4x	5.40	x	0.70	x	0.30 =	4.54
6x	3.90	x	0.80	x	0.30 =	5.62
4x	5.40	x	0.90	x	0.30 =	5.83
9x	3.60	x	0.85	x	0.30 =	8.26
7x	4.80	x	0.75	x	0.30 =	7.56
9x	2.90	x	0.65	x	0.30 =	5.09
Total =						46.94 ₇₂

② maint of corridor

52 sq ft - 21

2x	9x	4.60x	0.70	57.96
2x	8x	5.90x	0.80	75.52
2x	6x	6.10x	0.60	43.92
2x	7x	5.40x	0.65	49.14
2x	6x	3.80x	0.75	34.20
TOTAL				260.74

Continuation

Continuation