

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, गोगरी।

E-mail ID.- eerwdgogri@gmail.com

पत्रांक4168.....का0प्र0गोगरी,दिनांक.....19/12/2024

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, गोगरी।

सेवा में,

नोडल पदाधिकारी,
3054(MR)
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय:-

शीर्ष New Maintenance Policy-2018 under MR-3054 योजना अन्तर्गत राशि का अधियाचना समर्पित करने के संबंध में।

महाराज,

उपर्युक्त विषयक संबंध में कहना है कि शीर्ष New Maintenance Policy-2018 under MR-3054 योजना अंतर्गत कुल मो0 42,26,023=00 रुपये मात्र उपलब्ध कराने की कृपा की जाए। इस पत्र के साथ विहित प्रपत्र में अधियाचना राशि समर्पित की जा रही है।

सूचनार्थ सादर समर्पित।

अनु0- यथोक्त

Kur
18/12/24

विश्वासभाजन

Sax 18/12/24

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, गोगरी।

18/12/24

FORM GFR 19-A
(See Government of India's Decision (I) below Rule-150)
Form of Utilization Certificate up to the Dec. 2024
RWD, Works Divisio, Gogri.

Sl. No	Name of Scheme	Sanction No. & Date with Amount (in lacs Rs.)	Amount Received (in lacs Rs.)	Particulars
1	Construction of Rural roads New Maintenance Policy-2018 under MR-3054	Previous Allotment	Rs. 6204.57985 Lakh	Certified that out of Rs. 6290.92516 lacs of grants-in-aid sanctioned during the years 2019-20 in favors of E-in-C, RWD Bihar, Patna a sum of Rs. 6290.92516 lacs has been utilized for the purpose of MR(3054) Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 0.00 Lacs remaining unutilized at the end of the period under report.
		1. Letter No. 133, Date - 17.12.2024	Rs. 86.34531 Lakh	
	Total :-		Rs.- 6290.92516 Lakh	


1. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.


Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Superintending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer/ Executive Engineer.
- All other codal formalities have been observed.

2. Physical Progress achieved :-

- Construction of Road Works.
- Construction of CD works


D.A.O.
RWD Works, Division, Gogri


Executive Engineer
RWD Works, Division, Gogri



Baskar
18/12/24

Requisition Formate for Scheme Head - MR(3054) under Bihar Rural Road Maintenance Policy - 2018 (Initial Rectification and Surface Renewal)
Name of Works Division :- Gogri

SI No.	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No & Date	Administrative		Agreement Amount		Agreement No. & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in Percentage	Previous Total Alloted Amount (in Lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (In km)	Amount of (In Lakh)	Initial Rectification with Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/KH/GO G/24/0001	N.H. -107 to Farey Yadav Tola Road	20904501083	LI No.- 6120 Dated 04.12.2023	3.040	169.467	110.2333	25.13733	MBD/2023-24, Date - 16.03.2024	15.12.2024	18.09.2024	2837.968	25.106	5.05	65.47485	65.47485	42.26023	

Total = 42.26023

- 1 Signed Hard Copy and Soft Copy (in Excel) of recorded IRI is enclosed.
- 2 Up-to-date Physical Progress has been uploaded in MIS.


 Saroj Kumar
 Executive Engineer
 RWD, Works

MR 3054 (New)

M.B.No - 646

23-24

Schedule XLV-Form No. 134

NH. 107 to forestry yarday Joda Road

~~44503~~ ~~2712137~~

DIVISION

~~3495~~ ~~44503~~ ~~2712137~~

SUB-DIVISION

MEASUREMENT BOOK

M/S Ray Construction

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
grout (1.4) on brick					
work on sub structure					
— — — — —					
cut hole in the m.s					
P. no (25) item no (11)					
149.40 m ²					
② 221.70/m ² — 331222					
(18) Painting two coats					
with prime coat after					
filling the surface					
— — — — —					
cut hole in the m.s					
P. no (25) item no (12)					
149.40 m ²					
② 139.16/m ² — 207902					
(19) Planching of trees by					
the road side in					
0.60 m dia holes					
in depth — — — — —					
cut hole in the m.s					
P. no (25) item no (13)					
96.70					
② 1305.10/ea — 125290					
4					
10412840 =					
Add 18% S.F. + chdly					
S. Fee					
(+) 1978440 =					

Continuation 12391280 =

Continuation