

5th year maintenance

30

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1. Name of work: 5030 Bangri medaya school to mynni.					
Bangri Harizon Tola					
2. Name of agency: manjeet Kr					
3. Agreement No: 50/SD/2019-20					
4. Actual of completion: 08.12.2019					
measurement as below					
① Restoration of drain cuts with soil - cut fill					
	1x	30.0	0.75	0.30	6.75
	1x	20.80	0.75	0.30	4.68
	1x	12.50	0.75	0.30	2.81
	1x	18.50	0.75	0.25	3.46
	1x	10.20	0.72	0.25	1.83
	1x	20.80	0.75	0.30	4.68
	1x	1.50	0.70	0.25	0.26
	1x	1.56	0.70	0.25	0.27
	1x	1.50	0.70	0.25	0.26
					Qty = 24.524m ³
					say Qty = 24.51m ³
② maintenance of earth shoulder side fill					
	2x	30.0	0.75		45.0
	2x	30.0	0.75		45.0
	1x	20.50	0.75		15.375
	1x	18.60	0.70		13.02

Continuation C.O. Qty = 118.395m³

P.T.O.

Continuation