

M.M.G.S.Y (W.B)

M.B.No - 479
20-21

Schedule XLV Form No. 134
Rabhi Nagar to Gosai Sisbami

Division Gogai DIVISION

Sub. Division. Gogai SUB-DIVISION

M.B.No. 479

Measurement Book

Deo Enterprises

प्रमाणित किया जाता है कि इस
मापी पुस्तक में मशीन द्वारा अंकित
कुल-100 (एक सौ) पन्ने हैं जिसे
श्री अरविन्द कुमार, सहायक अभियंता
ग्रामीण कार्य विभाग कार्य अवर
प्रमंडल गोगरी को निर्गत किया
जाता है।

10.11.20
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
अवर प्रमंडल-गोगरी
Best
26/11/20

Sch. XLV - Form No. 134

प्रमंडल गोगरी DIVISION
अवर प्रमंडल गोगरी SUB-DIVISION

Measurement Book

No. 479

Name of Officer _____

1st on A/C Bill

Name of Work-

Situation of Work-

Agency by which work is executed-

Date of Measurement-

No. and date of agreement

(These four lines should be repeated at the commencement of the measurement relating to each work)

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - const. of					
road from Rabin Nagar					
to Golei Sirhan.					
Name of Agency - Deo Enterprises					
Pvt. Ltd. Ft - rate					
Vaikhno Devi Nagar, Chakhu-					
liani, P.O + P.S - Manzi					
Khagaria (Bihar)					
Agreement No: - 46580/2020-2021					

Date of commencement - 18.11.2020

Date of completion - 17.11.2021

Record measurement

Date - 20.09.2022

1. setting out pillars

Prvg. & fixing of working

benchmark pillars etc do -

do all comp. job -

i) working benchmark

pillars - 2.0 nos.

ii) Reference pillars -

8.0 nos.

Abstract of costs

① Restoration of rain
cuts/beroo - all costs -
at vide in the on B
P. no ① item no ①

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Limit 106.31 104.43 m²					42176
② 336.73/m ² — n					41430
② making up of borrow shoulder; Shifting excess soil from the shoulder — — all comp. on at vide in this m. g					
P. no ② item no ②					
255.50 m ²					
③ 59.66/m ² — n					32902
③ Patch repairs over bituminous surface with 20 mm — — all comp. on					
at vide in this m. g					
P. no ⑤ item no ③					
46.232 m ² ② 283.22/m ²					13094
④ maintenance of existing shoulder — — all comp. on					
at vide in this m. g					
P. no ⑤ item no ④					
250 m ② 2.69/m — n					672
⑤ maintenance of slab culvert at vide in this m. g					
P. no ⑤ item no ⑤					

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1 no @ 1126.67 ^{1130.67} / ea. —					1131.00 1137.00
(1) maintenance of slab					
culvert					
at vide in this n.s.					
P.no (55) item no (5)					
= 4 no @ 2329.20/ea. —					9317.20
(2) Maintenance of					
road sign					
at vide in this n.s.					
P.no (56) item no					
(7) = 0.21 km					
@ 1077.82 / km —					2262.92
(8) maintenance of					
200 m and iron stue					
at vide in this n.s.					
P.no (56) item no (8)					
= 0.25 km					
@ 625.87 / km —					1564.68
(9) cutting of branches					
of trees and shrubs					
at vide in this n.s.					
P.no (56) item no (9)					
= 4 no @ 109.74/ea. —					439.00
(10) white washing of					
parapet walls of					
C.D. work — see cert —					
at vide in this n.s.					

[illegible]