

# 4th Year Maintenance

53

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Maintenance of road from Jamuniya Tola Bandh to H/o Noti Mistri under MNOSY					
Agency - M/S K. P. Construction					
Agreement NO - 57 SBD/2018-19					
Date of start - 22/01/2019					
Actual date of completion - 22/10/2019					

## ① Restoration of Rain

ceits

1 X 6.15 X 1.20 X 0.30 =	2.21 $m^3$
1 X 9.00 X 1.15 X 0.25 =	2.58 $m^3$
2 X 8.15 X 1.10 X 0.25 =	4.48 $m^3$
1 X 10.00 X 0.90 X 0.30 =	2.70 $m^3$
2 X 7.10 X 1.15 X 0.30 =	4.90 $m^3$
3 X 9.10 X 1.10 X 0.25 =	7.42 $m^3$
1 X 10.00 X 1.00 X 0.30 =	3.00 $m^3$
1 X 6.10 X 0.80 X 0.25 =	1.20 $m^3$
2 X 11.00 X 1.20 X 0.25 =	6.60 $m^3$
1 X 6.50 X 0.75 X 0.30 =	1.46 $m^3$
2 X 8.00 X 1.20 X 0.30 =	5.76 $m^3$
3 X 12.00 X 0.90 X 0.30 =	9.72 $m^3$
1 X 7.50 X 1.25 X 0.25 =	2.34 $m^3$
2 X 9.50 X 1.20 X 0.30 =	6.84 $m^3$
3 X 8.25 X 1.15 X 0.30 =	8.54 $m^3$
2 X 15.00 X 1.10 X 0.30 =	9.90 $m^3$
3 X 6.50 X 1.20 X 0.25 =	5.85 $m^3$
4 X 9.00 X 1.20 X 0.30 =	12.96 $m^3$

Continuation

98.46  $m^3$

# Abstract of Cost

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of Raincets					
Q. V77B P53 (1) = 98.46 m <sup>2</sup>					
c. L. 36.5 = 25/11 m 359.63 = 00 ✓					
(2) Maintenance of earthen					
shoulder					
Q. V77B P54 (2) = 459.57 m <sup>2</sup>					
c. L. 54.37 m <sup>2</sup> - P. 2.4987 = 00 ✓					
(3) Maintenance of bitum					
surface road					
(1) Repair to pothole					
Q. V77B P55 (3) = 95.79 m <sup>2</sup>					
c. L. 28.6 = 92/11 m 274.84 = 00 ✓					
(ii) Maintenance of W.B.H					
road					
Q. V77B P55 (3) = 95.79 m <sup>2</sup>					
c. L. 384.81 m <sup>2</sup> - P. 3686.1 = 00 ✓					
(iii) Patch repair					
Q. V77B P55 (3) = 95.79 m <sup>2</sup>					
c. L. 271 = 15/11 m 2.25973 = 00 ✓					
(4) Maintenance of H.P.					
curbent					
Q. V77B P55 (4) = 2.74 m <sup>2</sup>					
c. L. 113 = 64/11 m 2263 = 00 ✓					
(5) White washing on					
Parapet of C.D					
Q. V77B P55 (5) = 28.54 m <sup>2</sup>					
c. L. 16.80 m - P. 479 = 02 ✓					
Continuation					
					154,010 = 01 ✓

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑥ cutting of branches of trees					
Q-V77BP 56(6) = 9 day					
C P- 107.48/each R- 967=0					
⑦ cutting of shrubs					
Q-V77BPL 56(5) = 19 day					
C P- 6.60/each R- 12.5=0					
⑧ Trimming of grass					
Q-V77BS 6(6) = 768 m <sup>2</sup>					
C P- 2.20/m <sup>2</sup> R- 1690=0					
⑨ Maintenance of road					
519m					
Q-V77BP 56(2) 1.522 Km					
C P- 1087=63/km R- 16.55=0					
⑩ Maintenance of 200m stone					
Q-V77BPL 56(7) = 0.274 Km					
C P- 749=00/km R- 2.05=0					
P- 158.652=0					
Less 0.05 /below					
P- 158.573=0					
<del>Shrub</del> 15.12.23					
<del>Shrub</del> 15.12.23					
Blades 15.12.23					
AC 2.1					
C/S					
✓					
✓					
17.12.24					
J.E					