

Const of Road from Bhagwati Ashram to Mushar Tola.

Schedule XLV-Form No. 134
UNDER - MMSY - (GEN)

7/2/2017 22/17 ५ ४४४२ ०००१

Executive Engineer

R. W. D. (W) Division

Darbhanga - 2

DIVISION

Manisachhi

SUB-DIVISION

Agency: → Sri Pratap Kumar Shandilya.

MEASUREMENT BOOK

1126

Abstract of Cost

43

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
[01] Restoration of Ram cotd / Berms with Soil/masonry Qty vide P-41 = 7375 72.78 Cum					
@ ₹407 = 70/Cum					→ ₹29672=00
[02] making up of Berms/ Shoulder Stripping Excav Soil from the Shoulder Vide P-41 = 406.00 Sq.m					
@ ₹60 = 58/Sq.m					→ ₹24595=00
[03] maintenance of CD work of HP Culvert = 04 No					
@ ₹1182 = 79 Each					→ ₹4731=00
[04] Trimming of grass & weeds from the Shoulder Vide P-42 = 14.40 Sq.m					
@ ₹22 = 37/Sq.m					→ ₹34=00
[05] White Washing of parapet Wall of CD work Vide P-42 = 82.56 Sq.m					
@ ₹17 = 10/Sq.m					→ ₹1412=00
Sub total					₹60444=00
Add GST @ 12%					₹7253=00
Add L.C @ 1%					₹604=00
Add S.F					₹215=00
					₹68516=00

Continuation

[illegible]

Continuation