

कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सुपौल।

पत्रांक...1652

सुपौल, दिनांक...18/12/2024

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल, सुपौल।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी
—सह—सचिव, नोडल पदाधिकारी,
ग्रामीण कार्य विभाग,
बिहार, पटना।

विषय :- शीर्ष MR-3054 (New Maintenance Policy-2018) योजना के अन्तर्गत स्वीकृत योजनाओं में आवंटन हेतु अधियाचना।

महाशय,

उर्पयुक्त विषयक संदर्भ में सूचित करना है कि शीर्ष MR-3054 (New Maintenance Policy-2018) के अन्तर्गत पथों का किये गये कार्य के भुगतान हेतु विहित प्रपत्र में अधियाचना प्रपत्र संलग्न की जा रही है।

अतः भवदीय से अनुरोध है कि उक्त राशि उपलब्ध कराने की कृपा की जाय ताकि संवेदक को कराये गये कार्य का भुगतान किया जा सके।

अनु० :- 1. उपयोगिता प्रमाण पत्र Form GFR 19

2. अधियाचना प्रपत्र।

विश्वासभाजन



कार्यपालक अभियंता
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, सुपौल।

38
18/12



Division - Supaul

Block of Circle - Madhepura

Sl No	Package No	Name of Road	Project ID as per MIS	Administrative Sanction Letter No & Date	Administrative Approval (AA)		Agreement Amount (in Lac)		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of RI (in mm/km)	Thickness of Bitumen (in mm)	Value of Bitumen Content in Percentage	Previous Total Allotted Amount (in lakh)	up-to-date expenditure as per MIS (in Lakh)	Requisition against work done (in Lakh)	Remarks
					Length (in km)	Amount of (in Lakh)	Initial Rectification surface Renewal (in Lakh)	5 Years Routine Maintenance (in Lakh)										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19
1	RM/SU/SUP/23/0003	Behta - Kulharya	21004903001	Lt-6120 Dt-04.12.2023	7.400	422.874	330.56771	59.34589	13MBD/2023-24 Dt-13.03.2024	12.12.2024	Surface Completed.	2427.36	25mm	5.2	0.00000	0.00000	140.00000	
2	RM/SU/SUP/24/0002	Bela srangar mothu panchayat rd 2 sa dhobihari jama wali path ka sas bhang	21004904023	Lt-6120 Dt-04.12.2023	0.987	66.484	44.50435	5.66369	01MBD/2024-25 Dt-16.07.2024	15.04.2025	Surface Completed.	2682.57	-	-	32.45256	32.45256	10.11245	
3	RM/SU/SUP/24/0002	T02 to Mahadalur Tola	21004913014	Lt-6120 Dt-04.12.2023	0.800	47.189	30.31841	5.5616	01MBD/2024-25 Dt-16.07.2024	15.04.2025	Surface Completed.	2512.5	-	-	15.46585	15.46585	10.15628	

- Signed Hard Copy and Soft Copy (in excel) of Recorded RI is enclosed.
- Up-to-date Physical Progress has been uploaded in MIS.


 Executive Engineer
 Rural Works Department
 Madhepura Division Supaul
 18/11/2024

***FORM GFR 19-A**
(See Government of India's decision (I) below rule- 150)
Form of Utilization certificate up to the month December 2024
PIU:- E.E RWD(W)DIV-Supaul

SL.NO.	Name of Schemes	Sanction No.& Date with Amount (In Lacs)	Amount received (In Lacs)	Particulars
1	2	3	4	5
1	New Maint. Policy-2018 (MR)	Lt.No-40 Dt-14.06.2021 Lt.No-52 Dt-24.08.2021 Lt.No-60 Dt-09.11.2021 Lt.No-05Dt-25.01.2022 Lt.No-20Dt-14.03.2022 Lt.No-35Dt-14.03.2023 Lt.No-72Dt-10.05.2023	11194.72013	Certified that out of Rs. 11194.72013 Lacs of grants-in-aid sanctioned during the years 2024-25 in favour of Executive Engineer R. W. D. Works Division, Supaul a sum of Rs 10770.78089 Lacs has been utilized for the purpose of New Maint. Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs. 423.93924 Lac remaining unutilized at the end of the period under report.
		TOTAL	11194.72013	

2. Certified that I have satisfied myself that the conditions on which the grant-in-aid was sanctioned have been duly fulfilled, are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kinds of checks exercised:-

- Works has been supervised by Executive Engineer / Superintending Engineer.
- Periodic as inspection has been conducted by Executive Engineer / Superintending Engineer.
- Construction materials have been tested.
- Measurements have been recorded in the MBs and test check conducted by the Assistant Engineer / Executive Engineer.
- All other codal formalities have been observed.

3. Physical Progress achieved:-

- Construction of Road Works.
- Construction of CD Works.


DIVISIONAL ACCOUNTS OFFICER

R.W.D. Works Division, SUPAUL


EXECUTIVE ENGINEER

R.W.D. Works Division, SUPAUL

Name of work : Belhi-Kuharia

Name of customer : Ganpati Constech Private Limited

(R)Rural Road		
Good	Average	Poor
< 4000	4001 - 5000	> 5000

Date	Time	Test No	Distance(m)	Total Distance(m)	Bump(m)	Speed(Km/Hr)	U/mmm/Km	Corrected IRI (mm/Km)	IRI	Status	Latitude	Direction	Longitude	Direction 1	Remarks
11/12/24	13 08 59	58	0	0	0.0 cm	14.6 Km/Hr	0.0 mm/Km	216	0.38	Good	26.2774254 N	86.5305407	E	Normal	Normal
11/12/24	13 10 33	58	100	100	22.0 cm	12.4 Km/Hr	2200.0 mm/Km	2257	3.13	Good	26.2774841	N	86.5305881	E	Normal
11/12/24	13 11 00	58	100	200	24.0 cm	13.2 Km/Hr	2400.0 mm/Km	2443	3.35	Good	26.2773074	N	86.5304410	E	Normal
11/12/24	13 11 28	58	100	300	21.0 cm	12.4 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26.2771084	N	86.5302897	E	Culvert
11/12/24	13 11 49	58	100	400	23.0 cm	17.2 Km/Hr	2500.0 mm/Km	2536	3.47	Good	26.2766535	N	86.530055	E	Normal
11/12/24	13 12 12	58	100	500	22.0 cm	15.8 Km/Hr	2200.0 mm/Km	2257	3.13	Good	26.2756421	N	86.5281459	E	Normal
11/12/24	13 12 36	58	100	600	21.0 cm	14.4 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26.2752724	N	86.5278087	E	Culvert
11/12/24	13 13 07	58	100	700	25.0 cm	12.1 Km/Hr	2500.0 mm/Km	2536	3.47	Good	26.2752873	N	86.5278678	E	Normal
11/12/24	13 13 38	58	100	800	24.0 cm	11.8 Km/Hr	2400.0 mm/Km	2443	3.35	Good	26.2759064	N	86.5284379	E	Normal
11/12/24	13 14 06	58	100	900	21.0 cm	12.8 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26.2686980	N	86.5247993	E	Normal
11/12/24	13 14 30	58	100	1000	27.0 cm	14.5 Km/Hr	2700.0 mm/Km	2721	3.89	Good	26.2686092	N	86.5248492	E	Culvert
11/12/24	13 15 03	58	100	1100	28.0 cm	10.9 Km/Hr	2600.0 mm/Km	2629	3.58	Good	26.2686095	N	86.5248480	E	Normal
11/12/24	13 15 31	58	100	1200	23.0 cm	12.8 Km/Hr	2300.0 mm/Km	2350	3.24	Good	26.2608761	N	86.5256534	E	Normal
11/12/24	13 15 58	58	100	1300	25.0 cm	13.4 Km/Hr	2500.0 mm/Km	2536	3.47	Good	26.2608810	N	86.5256475	E	Normal
11/12/24	13 16 21	58	100	1400	26.0 cm	15.7 Km/Hr	2600.0 mm/Km	2629	3.58	Good	26.2591431	N	86.5271846	E	Normal
11/12/24	13 16 58	58	100	1500	20.0 cm	9.8 Km/Hr	2000.0 mm/Km	2072	2.89	Good	26.2591473	N	86.5271794	E	Normal
11/12/24	13 17 28	58	100	1600	26.0 cm	11.8 Km/Hr	2600.0 mm/Km	2629	3.58	Good	26.2555990	N	86.5318942	E	Normal
11/12/24	13 17 55	58	100	1700	21.0 cm	12.9 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26.2765491	N	86.5297746	E	Normal
11/12/24	13 18 19	58	100	1800	25.0 cm	15.3 Km/Hr	2500.0 mm/Km	2536	3.47	Good	26.2718874	N	86.5262734	E	Normal
11/12/24	13 18 43	58	100	1900	24.0 cm	14.8 Km/Hr	2400.0 mm/Km	2443	3.35	Good	26.2716893	N	86.5251324	E	Normal
11/12/24	13 19 14	58	100	2000	20.0 cm	11.4 Km/Hr	2000.0 mm/Km	2072	2.89	Good	26.2716485	N	86.5252470	E	Normal

11/12/24

B

Name of work : Belhi-Kulharia

Name of customer : Ganpati Constech Private Limited

(R)Rural Road

Good	Average	Poor
< 4000	4001 - 5000	> 5000

11/12/24	13 19 36	58	100	2100	21.0 cm	16.0 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26 2718565	N	86 5253476		
11/12/24	13 19 56	58	100	2200	26.0 cm	18.3 Km/Hr	2600.0 mm/Km	2629	3.56	Good	26 2718658	N	86 5253245	E	Culvert
11/12/24	13 20 16	58	100	2300	22.0 cm	17.8 Km/Hr	2200.0 mm/Km	2257	3.13	Good	26 2591456	N	86 5271895	E	Normal
11/12/24	13 20 34	58	100	2400	26.0 cm	19.8 Km/Hr	2600.0 mm/Km	2629	3.56	Good	26 2591450	N	86 5271854	E	Normal
11/12/24	13 20 57	58	100	2500	30.0 cm	15.9 Km/Hr	3000.0 mm/Km	3000	4.03	Good	26 2591439	N	86 5271862	E	Normal
11/12/24	13 21 16	58	100	2600	19.0 cm	17.4 Km/Hr	1900.0 mm/Km	1979	2.78	Good	26 2591456	N	86 5271856	E	Normal
11/12/24	13 21 38	58	100	2700	21.0 cm	17.8 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26 2591465	N	86 5271840	E	Normal
11/12/24	13 21 56	58	100	2800	28.0 cm	18.3 Km/Hr	2800.0 mm/Km	2814	3.81	Good	26 2591450	N	86 5271849	E	Normal
11/12/24	13 22 17	58	100	2900	23.0 cm	18.5 Km/Hr	2300.0 mm/Km	2350	3.24	Good	26 2591495	N	86 5271843	E	Normal
11/12/24	13 22 40	58	100	3000	33.0 cm	15.7 Km/Hr	3300.0 mm/Km	3278	4.36	Good	26 2757742	N	86 5284379	Culvert	
11/12/24	13 23 03	58	100	3100	21.0 cm	15.6 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26 2757742	N	86 5281048	E	Normal
11/12/24	13 23 35	58	100	3200	30.0 cm	15.9 Km/Hr	3000.0 mm/Km	3000	4.03	Good	26 2759410	N	86 5281459	E	Normal
11/12/24	13 24 12	58	100	3300	19.0 cm	17.4 Km/Hr	1900.0 mm/Km	1979	2.78	Good	26 2759084	N	86 5284379	Normal	
11/12/24	13 24 58	58	100	3400	28.0 cm	18.3 Km/Hr	2800.0 mm/Km	2814	3.81	Good	26 2764742	N	86 5284022	E	Normal
11/12/24	13 25 17	58	100	3500	23.0 cm	18.5 Km/Hr	2300.0 mm/Km	2350	3.24	Good	26 2764742	N	86 5284958	E	Normal
11/12/24	13 25 40	58	100	3600	33.0 cm	15.7 Km/Hr	3300.0 mm/Km	3278	4.36	Good	26 2762873	N	86 5284750	E	Normal
11/12/24	13 26 03	58	100	3700	21.0 cm	15.6 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26 2752724	N	86 5278087	E	Normal
11/12/24	13 26 35	58	100	3800	30.0 cm	15.9 Km/Hr	3000.0 mm/Km	3000	4.03	Good	26 2756421	N	86 5281459	E	Normal
11/12/24	13 27 12	58	100	3900	19.0 cm	17.4 Km/Hr	1900.0 mm/Km	1979	2.78	Good	26 2756459	N	86 5281423	E	Normal
11/12/24	13 28 07	58	100	4000	25.0 cm	12.1 Km/Hr	2500.0 mm/Km	2536	3.47	Good	26 2752724	N	86 5278087	E	Culvert
11/12/24	13 28 38	58	100	4100	24.0 cm	11.8 Km/Hr	2400.0 mm/Km	2443	3.35	Good	26 2752478	N	86 5278458	E	Normal
11/12/24	13 28 06	58	100	4200	21.0 cm	12.8 Km/Hr	2100.0 mm/Km	2165	3.01	Good	26 2756460	N	86 5273548	E	Normal

11/12/24

8

Name of work : Belhi-Kulharia

Name of customer : Ganpati Constech Private Limited

(R) Rural Road

Good

Average

Poor

< 4000

4001 - 5000


> 5000

11/12/24	13 29 30	58	100	4300	27 0 cm	14 5 Km/Hr	2700 0 mm/Km	2721	3 88	Good	26 2752724	N	86 5278087	E	Normal
11/12/24	13 30 03	58	100	4400	28 0 cm	10 9 Km/Hr	2800 0 mm/Km	2814	3 81	Good	26 2776777	N	86 5275306	E	Normal
11/12/24	13 30 31	58	100	4500	26 0 cm	12 8 Km/Hr	2800 0 mm/Km	2829	3 58	Good	26 2766690	N	86 5274314	E	Normal
11/12/24	13 30 58	58	100	4600	25 0 cm	13 4 Km/Hr	2500 0 mm/Km	2536	3 47	Good	26 2758472	N	86 5281457	E	Normal
11/12/24	13 31 21	58	100	4700	26 0 cm	15 7 Km/Hr	2800 0 mm/Km	2829	3 58	Good	26 2749822	N	86 5219431	E	Normal
11/12/24	13 31 58	58	100	4800	20 0 cm	9 8 Km/Hr	2000 0 mm/Km	2072	2 88	Good	26 2808815	N	86 5256479	E	Normal
11/12/24	13 32 28	58	100	4900	26 0 cm	11 8 Km/Hr	2800 0 mm/Km	2829	3 58	Good	26 2808756	N	86 5256590	E	Normal
11/12/24	13 32 55	58	100	5000	21 0 cm	12 9 Km/Hr	2100 0 mm/Km	2165	3 01	Good	26 2866080	N	86 5248491	E	Normal
11/12/24	13 33 18	58	100	5100	28 0 cm	18 3 Km/Hr	2800 0 mm/Km	2814	3 81	Good	26 2866080	N	86 5248506	E	Normal
11/12/24	13 33 36	58	100	5200	25 0 cm	13 4 Km/Hr	2500 0 mm/Km	2536	3 47	Good	26 2866080	N	86 5247986	E	Normal

11/12/24

86 5247986

Name of Customer: Ganpati Constech Private Limited, Machine no: 19187, Road: Boli-Katharia, Date: 11-12-24, Section No: 58, Equation: $Y=0.925X+215.8$



[Handwritten signature]
11/12/24
SS

[Handwritten signature]