

1st Year Maintenance

36

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work - Corbels					
Year from To	10				
Relative path					
Agency - G. Ram Kumar					
Ass. No - 29/53D/2020-21					
D.O.S - 31.8.20					
D.O.C - 30.8.21					
D.O. Actual Comp - 31.3.22					
				12.1.23	
(1) Restoration of rain water					
(15.1) berm with soil -					
	25	2.50	0.30	0.25	4.69 m ²
	38	1.75	0.50	0.30	9.97
	43	2.0	0.50	0.30	12.90
				T =	27.56 m ²
(15.2) Making up of Berm					
Shoulder stripping excess					
soil from the shoulder					
	3	2	0.30	0.25	1.80 m ²
	27	4.0	0.30		32.40
	2	2	30.0	0.45	54.0
	1	25.0	0.50		12.50
	17	9.0	0.30		45.90
					146.60 m ²
(15.3) Put repair over					
with 20mm M.S.S. - all -					
	5	1.25	1.0		6.25 m ²
	12	1.0	1.0		12.0
					18.25 m ²

Continuation

Attended
12/12/14
ED