

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/R- Maint. of road from Dihuli Majhampura road to Kopa Mphadait tola.					
Agency: Siga Enterprises and Construction. Gada Enterprises.					
Ag. No.: OSKSD / MMSY NBN 12021-22					
Date of actual Completion: 22/07/2022					
Maint. Start: 25/07/2023 to 22/07/2024					

① Restoration of road cuts/berms with soil masonry. - 2/1					
14.0 Nos	X	6.50	X	0.350	X 0.80 = 7.962 m ³
12.0 Nos	X	8.10	X	0.400	X 0.20 = 7.776 m ³
7.0 Nos	X	4.50	X	0.350	X 0.250 = 2.756 m ³
6.0 Nos	X	9.10	X	0.450	X 0.250 = 6.142 m ³
9.0 No	X	7.50	X	0.350	X 0.80 = 5.906 m ³
					30.539 m ³
					30.78 m ³
② Making up of berms/shoulder stripping excess soil from the shoulder - - - - 2/1					
8x		8.50	X	0.950	= 69.40 m ²

Continuation

2nd Year Maintenance Bill

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1/1) Restoration of earthen cuts					
Qty via TMB P- (14)					
30.38 m ³ @ RS 404.06				2 RS	12275.0
(2/15.2) Making up of berms/					
Shoulder, stripping excess soil					
Qty via TMB P- (15)					
168.75 m ² @ RS 60.28				2 RS	10172.0
(3/15.5) Repair of pot holes filled					
with 75mm, - - - C/S					
Qty via TMB P- (45)					
0.07 m ³ @ RS 9909.11				2 RS	694.0
(4/15.3) Patch repair over					
potholes with 20mm - - C/S					
Qty via TMB P- (45)					
23.44 m ² @ RS 254.16				2 RS	5958.0
(5/15.3.1) Patch repair over bitu-					
minous surface - - - C/S					
Qty via TMB P- (45)					
23.44 m ² @ 270.10				2 RS	6339.0
(6/10x) Crack Sealing - - C/S					
Qty via TMB P- (45)					
350.0 M @ RS 3.70				2 RS	1295.0
(7/10.10) Repair of O/D joint					
sealing - - - C/S					
Qty via TMB P- (45)					
2.10.0 M @ RS 24.13				2 RS	506.7
(8/15.7) Maintenance of colour					
Qty via TMB P- 45					
2.01103 @ RS 1166.58				2 RS	2355.0

Continuation

RS 444.95-0



Continuation