

29/12/2018

Schedule XLV-Form No. 134

14/12/2018
(14/12/2018)

Rw. Thag Thag Thag Thag DIVISION

Meelha Thag SUB-DIVISION

MEASUREMENT BOOK

1644

Continuation

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	24	5.634	0.300		3.38 M ²
(20) N/A to washing of parapet					
Wall of C.D. Work H.P.					
convert as per EI					
2424	6.154	0.40			9.84 M ²
242424	6.154	0.600			29.52 "
242424	0.400	0.600			1.92 "
					41.28 M ²
Sameer 01/08/2023 01/08/23 AE					
ABSTRACT OF COST.					
3rd year maintenance					
(1/1) restoration of drain cut bench					
with soil maximum as per EI					
at site vide T.M.B.P-49(1)					
55.14 M ³ @ 380.59/M ³ Δ					20932.00
(2/2) making up bearing slab					
as per EI					
at site vide T.M.B.P-50(2)					
283.73 M ² @ 58.37/M ² Δ					16561.00
(3/3) Repair of pot hole with W.I.					
75mm BM as per EI					
at site vide T.M.B.P-50(3)					
3.16 M ³ @ 11726.44/M ³ Δ					37049.00
(4/4) patching over pot hole with					
max. seal surfacing as per					
EI					

Continuation

Cost 74542.00

Continuation