

4th year Maintenance

83

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Content of area
	No.	L.	B.	D.	
New Maintenance of Road System					
Majhar chaur Bakiya Kabachtem					
se matiyani (Bokya)					
Tola dhuniya Bokya North					
Agency - New Construction					
Agg No: 16 SBD/2018-19					
Date of start: 11/08/2018					
Actual date of Completion: 09/09/2020					
period — 09/09/2023-8/9/2024					
① Restoration of Road cuts with					
Soil, medium, gravel etc.					
3 Nos x 20.00m x 1.20 x 0.30 = 36.00m					
2 x 2 x 30.00m x 1.10 x 0.30 = 39.60m					
6 Nos x 8.50m x 1.25m x 0.40 = 25.50m					
10 Nos x 12.30m x 1.10m x 0.30 = 40.59m					
15 Nos x 8.00m x 1.20 x 0.300 = 43.20m					
2 x 5 x 30.00m x 1.25 x 0.30 = 112.50					
10 Nos x 9.50m x 1.00 x 0.300 = 28.50m					
2 x 3 x 30.00m x 1.25 x 0.30 = 60.75					
3 Nos x 17.00 x 1.00 x 0.30 = 15.30m					
5 Nos x 22.50 x 1.30 x 0.40 = 58.5m					
4 Nos x 15.00m x 1.20 x 0.300 = 21.60					
Qty - 482.04m					
Grand Qty - 479.28m					

Abstract of Cost

86

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of kerbs					
479.25 m ³ @ VTM P(83)					
@ Rs 351 = 43/m ³ Rs — 168423 =					
② Maintenance of Earth					
Spall					
2652.90 m ² @ VTM P(84)					
@ Rs 54 = 27/m ² Rs — 1439732 =					
③ Repair of pot holes Residual					
filled material					
249.56 m ² @ VTM P(84)					
@ Rs 284 = 88/m ² Rs — 71592 =					
④ P.V. curbs laying Residual					
existing Bituminous surface					
311.95 m ² @ VTM P(85)					
@ Rs 113 = 63/m ² Rs — 35447 =					
⑤ P.V. curbs laying Residual					
existing Bituminous surface					
311.95 m ² @ VTM P(85)					
@ Rs 102 = 04/m ² Rs — 318312 =					
⑥ Maintenance of Road sign					
3.55 km @ VTM P(85)					
@ Rs 1024 = 25/km Rs — 368625 =					
⑦ Maintenance of road					
stone pit					
0.639 km @ VTM P(85)					
@ Rs 643 = 38/Lm Rs — 411 =					

Continuation



