

Sthy car Maintenance

33.

Sch.XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/w - Maintenance of					
Road of 20m					
Gralimpur Sawadh					
Kemalar Se Gralimpur					
Bhumihar to lotok					
jane coali path					
Agency - Ashok Kr Singh					
Agg No - 05 SRD 119-20					
Date of Commencement - 28/2/19					
Time of Completion - 18/4/20					

① Restoration of Rain Cuts

$$18 \times 6.00 \times 0.75 \times 0.30 = 24.30$$

$$20 \times 4.10 \times 1.00 \times 0.30 = 25.80$$

$$50 \times 2.00 \times 1.20 \times 0.20 = 24.00$$

$$\text{Total} = 74.13 \text{ m}^3$$

② Maintenance of Earthen Shoulder

$$8 \times 4.00 \times 0.80 = 25.60$$

$$9 \times 6.00 \times 0.90 = 48.60$$

$$7 \times 5.00 \times 0.80 = 28.00$$

$$17 \times 8.00 \times 0.74 = 100.64$$

CA 111111