

2nd year Maintenance Bill

49

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work:- Maint. of Road from					
Bahurwa Mahadalit					
Tola To Goriyasi					
N/Agency:- Pappu kr. Singh.					
Dhandaha, Purnea.					
Agreement No. - 11 SBD/2016-17					
Date of Start - 03.08.2016					
Date of Comp. - 02.08.2017					
Act. Date of Comp. - 28.03.2018					
① Restoration of rain					
Cuts in the shoulder					
Berms with soil - -					
- - - - -					
15 x 2.20 x 1.125 x 0.40 - 14.85 m ³					
4 x 8.00 x 1.00 x 0.300 - 9.60 m ³					
2 x 15.00 x 1.125 x 0.250 - 8.437 m ³					
6 x 5.60 x 1.10 x 0.500 - 18.48 m ³					
10 x 1.80 x 0.70 x 0.300 - 3.78 m ³					
8 x 3.20 x 1.00 x 0.250 - 6.40 m ³					
12 x 4.30 x 1.125 x 0.250 - 14.512 m ³					
4 x 11.00 x 0.60 x 0.300 - 7.92 m ³					
5 x 5.75 x 1.100 x 0.300 - 9.487 m ³					
Continuation					93.466 m ³

2nd year Maintenance Bill.

53

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
<u>ABSTRACT OF COST</u>					
N/Work: Maintenance of Road from Bahurwa Mahadalit Tola to Gorhyari					
N/Agency: Pappu Kumar Singh Dhamelaha, Purnee.					
Agg. No - 11 SBD/2016-17					
Date of Start - 03.08.2016					
Date of Completion - 02.08.2017					
A.D.O. Completion - 28.03.2018					
① Restoration of rain Cuts in the shoulders Berms with Soil -					
- - - - - 1st					
Qty 93.468 m ³					
@ Rs 323.28/m ³ - Rs. 30214 = 46					
② Making up of Berms shoulders stripping excess soil -					
- - - - - 1st					
Qty 442.691 m ²					
@ Rs 5014/m ² - Rs 22196 = 52					
③ Patch repair over bituminous Surface with 20 mm premix Carpet - - -					

Continuation

52410 = 98

Continuation