

3rd year Maintenance Bill

58

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work: Maintenance of Road					
from Gopalpur pith					
Sadak to Balia Bagg					
TK -					
Agency: Chandan Kumar Singh					
Charanpatti, Udaipur					
Ag. No. 63 SDD/2018-19					
D. of Start - 13.10.2018					
A.D. of Comp. 19.08.2021					
① Rectification of road					
Cuts with Soil - - -					
- - - - -					
3 x 7.30 x 1.125 x 0.300 -					6.57 m ³
5 x 4.70 x 1.100 x 0.300 -					7.76 m ³
7 x 3.50 x 1.125 x 0.300 -					8.27 m ³
6 x 5.25 x 1.05 x 0.300 -					9.92 m ³
4 x 6.75 x 1.0 x 0.250 -					6.75 m ³
3 x 5.45 x 1.05 x 0.300 -					5.75 m ³
					44.42 m ³
② Making up of Burm/Shoulder					
stripping - - - - -					
5 x 7.70 x 1.125 -					44.31 m ²
6 x 8.30 x 1.125 -					56.63 m ²

Continuation

300 year Maintenance Bill.

ABSTRACT OF COST

62

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work: Maintenance of Road					
from Gopalpur Pith					
Sadar to Balu					
Basq. Pak -					
Agencyr Chander Kumar Singh					
Chamrahatti, Uderishungri					
Medhepura.					
Ag. No. - 63 SBD/2018-19					
D. of Start - 13.10.2018					
A. D. of Comp. - 19.08.2021					
① Restoration of rain cuts					
with soil - - - -					112
✓ Amb. 58 Qty 44.42 m ²					
CR 355.25/m ² - - - -					16224.50
② Making up of Berms					
Shoulders stripping					
excess soil - - - -					112
✓ Amb. 59 Qty 386.83 m ²					
CR 54.76/m ² - - - -					28957.50
③ Patch repair over					
bituminous surface					
- - - - -					112
✓ Amb. 59 Qty 42.14 m ²					
CR 212.76/m ² - - - -					8940.50
④ Repair of pot holes -					
✓ Amb. 59 Qty 42.14/m ²					
CR 323.90/m ² - - - -					13649.50
CR 339.96/m ² - - - -					14225.50
Continuation					66440.50
					59764.50

