

3rd year Maintenance Bill

59

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/Work: Maint. of Road from Khawari Mahadalit Tola to Nasayanpur Basa (MNGS) SC					
N/Agency: Pappu Kumar Singh Dhandeha, Purnea.					
Agreement No. - 125BA/2016-17					
Date of Start - 02/08/2016					
Date of Completion - 02/08/2017					
A. D. O. Completion - 15/10/2017					
① Restoration of drain cuts with shoulder Soil - - - - - G.P.					
10 x 6.50 x 1.50 x 0.300 -					18.58 m ³
5 x 4.50 x 1.125 x 0.300 -					7.762 m ³
6 x 12.50 x 0.900 x 0.400 -					25.92 m ³
3 x 15.50 x 1.50 x 0.350 -					15.78 m ³
8 x 6.50 x 1.125 x 0.250 -					14.625 m ³
2 x 7.50 x 1.125 x 0.250 -					4.419 m ³
12 x 4.50 x 1.125 x 0.300 -					16.128 m ³
2 x 20.50 x 1.50 x 0.200 -					8.50 m ³
4 x 5.50 x 1.200 x 0.250 -					6.60 m ³
3 x 8.50 x 1.50 x 0.300 -					7.20 m ³
6 x 4.30 x 1.125 x 0.300 -					8.707 m ³

Continuation

Continuation

300 year Maintenance Bill

64

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ABSTRACT OF COST					
① Restoration of rain cuts with soil					
- - - - -					
- - - - -					
VTMBP-60 Qty 157.87 m ³					
@ Rs 323 = 28/m ³ — Rs 49028 = 84					
② Making up of Berms Shoulder, stripping excess soil					
- - - - -					
VTMBP-60 Qty 665.44 m ²					
@ Rs 50 = 74/m ² — Rs 33365 = 16					
③ Patch repair over pot holes with 20 mm premix Caspex					
- - - - -					
VTMBP-61 Qty 118.71 m ²					
@ Rs 276 = 20/m ² — Rs 32787 = 70					
④ Patch repair over bituminous surface with 20 mm premix Caspex					
- - - - -					
VTMBP-62 Qty 118.71 m ²					
@ Rs 298 = 69/m ² — Rs 35457 = 48					
⑤ Maintenance of Ch work in Home pipe Culvert					
- - - - -					
VTMBP-62 Qty 3.00 m					
@ Rs 910 = 95/m — Rs 2732 = 85					
Continuation					
					153372 = 03

Continuation