

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
	<u>4th year Maintenance Work</u>				
<u>N/W:- Conn^g flood from Suthare to Bhumihar Tala.</u>					
<u>Agency:- Mandy Kr. Mazal.</u>					
<u>Agg. No:- S.B.D. 74 / 019-20</u>					
<u>Maintenance period:- 15.6.23 to 14.6.24</u>					
<u>Measurement</u>					
<u>1) Restoration of Rain cult.</u>					
$20 \times 5.70 \times 0.90 \times 0.30 = 43.09 \text{ m}^3$					
$18 \times 4.30 \times 0.80 \times 0.30 = 16.52 \text{ m}^3$					
$16 \times 3.60 \times 0.70 \times 0.30 = 12.10 \text{ m}^3$					
$12 \times 5.20 \times 0.90 \times 0.30 = 16.85 \text{ m}^3$					
$14 \times 3.35 \times 0.90 \times 0.30 = 12.66 \text{ m}^3$					
$= 101.22 \text{ m}^3$					
<u>2) Making up Borm/Shoulder</u>					
$16 \times 4.70 \times 1.0 = 75.20 \text{ m}^2$					
$18 \times 5.20 \times 0.90 = 84.24 \text{ m}^2$					
$12 \times 3.90 \times 0.80 = 37.44 \text{ m}^2$					
$18 \times 4.05 \times 1.0 = 72.90 \text{ m}^2$					
$= 269.78 \text{ m}^2$					
<u>3) Patch Repair over potholes</u>					
$6 \times 2.50 \times 2.20 = 33.00 \text{ m}^2$					
$5 \times 2.30 \times 2.0 = 23.00 \text{ m}^2$					
$= 56.00 \text{ m}^2$					
<u>4) Maintenance of B. T. Surface Road.</u>					
$3 \times 5.0 \times 3.75 = 56.25 \text{ m}^2$					

Continuation

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
⑤ Maintenance of H.P. Culvert					
⑥ Maintenance of H.P. Road sign					
⑦ Cutting of branches of trees shrub					
⑧ White wash of c.d. Panchayat well					
⑨ Restoration of Rain cut					
⑩ Making up Borm/Shoulder					
⑪ Patch Repair on bit holes					
⑫ Maintenance of B. T. Surface Road					
⑬ Maintenance of H.P. Culvert					

Continuation

Rs 88686.0

d) Bmcd 1102 - 0.017 MT Continuation

$$\begin{array}{r} 141624 \\ \times 2 \\ \hline 283248 \end{array}$$