

Name of book — Measurement & to Structural

Agency — Sri Lanka

Measurement Book

Schedule XLY-Form No. 134

14/14/2014 (SC)

DIVISION

Sidda 119

SUB-DIVISION

1136

mmmsy

m.B. No-


2036

and your signature

55

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work	Construction of road				
	for Nandurthi to Singur				
	Under masonry				
Name of pay	Anp. Lal.				
	Ag. No. 1530/11/65/row-2				
Date of Commencement	11/9/2016				
Actual Date of Completion	11/2/2017				
$\frac{1}{4}$	Restoration of rain cul				
	with cul - L				
	4x	30.0x	0.9x	0.3x	32.40
	1x	25.2x	0.75x	0.3x	5.675
	1x	18.9x	0.9x	0.25x	4.25
	1x	17.5x	0.5x	0.25x	2.192
	2x	30.0x	0.9x	0.3x	16.20
					60.715
$\frac{2}{4}$	Making up of subgrade				
	1x	18.9x	0.9x		17.01
	1x	14.0x	0.75x		10.50
	5x	30.0x	0.9x		135.00
	1x	21.2x	1.0x		21.20
	2x	30.0x	0.9x		54.00
	1x	22.5x	0.75x		16.875
	1x	24.1x	0.9x		21.69
					278.27

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
3/6	P.L.L. ref. on				
	P.L. 2.00				
	1 x 3.1	1.2			3.72
	1 x 5.1	1.4			7.14
	1 x 2.2	1.0			2.2
	1 x 3.7	1.5			5.55
	1 x 5.0	1.0			5.0
					<u>23.61</u>
4/6	Maintenance of D. 20				
	H.P. Cut				4
5/7	Maintenance of S. 16				
	Cut				<u>2</u>
6/10	Cut of Area of Trees				<u>3</u>
7/12	Maintenance of S. 16				
	Planted trees... 1/2				<u>70</u>
	Seepage Cut				
①	E.V. - 49.22	34	81/3		171320
②	Cut. 0.63	51	44/3		322
					1035
	Have. S.G. for 1/2				<u>20420</u>
 4/4/2024  10/10/24					
Continuation					

[illegible]

Continuation

7th Std
 ① E/w - 42-2-3
 ② C/f - 0.63-3
 ③ Port 0.04 m/s
 25/04/24
 AT