

मन्वी

Khakhanchua te Rahim bighe.
M/S Vinay Construction

Schedule XLV-Form No. 134

E. E R W D, Pargauli DIVISION

A. E. Cobincha SUB-DIVISION

Measurement Book

M.B.No.

926

(Sc)

324 year work bill

57

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
N/W side - front of Road from.					
1st to Khadija to Rahim Basha.					
Agency - M/S Vinyay Control.					
15-10 - 20/8/2019/2020					
Actual date of comp/elm - 25/08/2020					

Measurement

(1/1) Restoration of Rainwater do -					
do -					
1x	12.25	1.20	0.60	=	8.82m ³
3x	9.90	1.15	0.55	=	18.785m ³
2x	11.25	1.25	0.50	=	14.063m ³
6x	7.90	1.10	0.45	=	23.463m ³
2x	8.95	1.15	0.50	=	10.293m ³
5x	9.95	1.30	0.65	=	42.038m ³
2x	8.75	1.20	0.60	=	12.60m ³
1x	7.25	1.10	0.50	=	4.386m ³
1x	8.75	1.30	0.65	=	148.623m ³

(2/2) Mound of earth shoulder					
do - do -					
1x	15.95	1.25		=	19.938m ²
2x	10.95	1.30		=	28.47m ²
3x	9.95	1.35		=	80.798m ²
5x	12.90	1.20		=	77.40m ²
6x	9.70	1.15		=	66.93m ²
7x	8.95	1.25		=	78.313m ²
6x	14.25	1.20		=	102.60m ²
5x	16.25	1.25		=	101.563m ²
Continuation				=	556.012m ²

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
					$B.P. = 586.012 m^2$
	5	14.95	1.25		$= 93.438 m^2$
	4	18.70	1.30		$= 97.24 m^2$
	3	14.10	1.10		$= 46.53 m^2$
	2	18.90	1.20		$= 45.36 m^2$
					$= 838.58 m^2$
(5/3) repairs to gable holes by removal of double timbered roof					
	1	9.25	1.90		$= 17.575 m^2$
	1	8.15	1.55		$= 12.633 m^2$
	2	4.25	1.30		$= 11.08 m^2$
	3	5.90	1.35		$= 23.895 m^2$
	3	6.75	1.40		$= 28.35 m^2$
					$= 116.128 m^2$
(5/4) repairs of wing and gable roof					
	1	9.25	1.90		$= 17.575 m^2$
	1	8.15	1.55		$= 12.633 m^2$
	2	4.25	1.30		$= 11.08 m^2$
	3	5.90	1.35		$= 23.895 m^2$
	3	6.75	1.40		$= 28.35 m^2$
	1	18.10	1.25		$= 22.625 m^2$
					$= 116.128 m^2$
(5/5) patching repairs on chimney					
(5/6) patching and making on BT					
	2	2	10	30	$\times 0.10 = 120.00 m^2$
	2	2	10	30	$\times 0.10 = 120.00 m^2$

Continuation

Continuation

ABSTRACT 012 003

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
1/1) Restoration of Rain cuts					
The - do -					
TMB, P-57 = 148.623 m ³					
@ 280.52/m ³ = Rs 56654 -00					
2/1) Making up loss of Mahmul of eastern shoulder					
TMB, P-58 = 838.58 m ²					
@ 57.53/m ² = Rs 48244 -00					
3/3) Repair of pot holes by removal of failed do					
TMB, P-58 = 116.128 m ²					
Lined to 113.24 m ²					
@ 251.35/m ² = Rs 28458 -00					
4/4) Repair of potholes on sub-grade filled with bitumen					
TMB, P-58 = 116.128 m ²					
Lined to 113.24 m ²					
@ 247.56/m ² = Rs 28028 -00					
5/6) Road Making on BT					
TMB, P-59 = 322.00 m ²					
@ 829.00/m ² = Rs 2,66,938 -00					
11) Road Making on EC					
TMB, P-59 = 110.00 m ²					
@ 939.00/m ² = Rs 1,03,290 -00					
6/14) Trimming of grass & weeds					
TMB, P-59 = 1405.56 m ²					
@ 2.18/m ² = Rs 3064 -00					
= Rs 5,34,571 -00					

Continuation

