

1st year Maintenance Bill

85

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work - Maint. of Road from Parail to Parail se Baghara Khagasiya Simarok.					
Agency: Bimal Kishore Gauram Madhepura.					
Aggr. No. - 15 CBP/2021-22					
D. of Start - 11.06.2021					
A.D. of Comp. - 16.06.2022 -					
① Restoration of soil cuts with soil - - - - -					
2x2720.0x1.125x1.25x0.06					
					= 137.70 m ³
② Making up of Berms/Shoulders - - - - -					
2x2920x1.125x1.25x0.10					
					= 821.25 m ³
③ Patch repair over pot holes - - - - -					
2720.0x3.75x1.25x0.005					
					= 63.75 m ³

Continuation

1st year of maintenance
Abstract of Cst.

87

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Work: Maintenance of Road from Parail to Parail Je Beghara Khaganya Singh Tal -					
Agency: Bimal Kishor Gautam Madhepura.					
Ag. No. - 15 EBD/2021-22					
D. of Start - 11.05.2021					
A. D. of Comp. 06.08.2022					
① Restoration of rain cuts with soil -					
- - - - - 412					
Vol. of 85 Qty 137.70 m ³					
CRs 404.06 / m ³ - - -					55639/-
② Making up of Berms shoulders - - - 412					
Vol. of 85 Qty 821.25 m ³					
CRs 60.28 / m ³ - - -					49505/-
③ Patch repair over pot holes with 75mm					
- - - - - 412					
Vol. of 85 Qty 63.75 m ³					
CRs 224.12 / m ³ - - -					14288/-

Continuation

0.0%

9/10/24
S.E

09/10/14
AB

~~cap~~
30. W

Material Statement

$$E_w = 228.46 \text{ m}^3$$

s/chips	-	1.73	10
---------	---	------	----