

# 2nd year maintenance

52

Sch. XLV-Form No. 134

| Particulars                       | Details of actual measurement |          |        |        | Contents of area     |
|-----------------------------------|-------------------------------|----------|--------|--------|----------------------|
|                                   | No.                           | L.       | B.     | D.     |                      |
| Name of work- Maint. of road from |                               |          |        |        |                      |
| Kadamwa                           | 101a                          | (50'11") | to     | Loss.  |                      |
| Agency- Shri Ashwani Krs. Chind.  |                               |          |        |        |                      |
| Agg. No- 47580/ MMMSY/ 2021-22.   |                               |          |        |        |                      |
| Date of start- 03/06/2021.        |                               |          |        |        |                      |
| Actual Completion- 01/03/2022.    |                               |          |        |        |                      |
| Record Entry                      |                               |          |        |        |                      |
| 1. Restoration of rain            |                               |          |        |        |                      |
| cuts -do-                         |                               |          |        |        |                      |
|                                   | 6x                            | 3.46     | x 1.15 | x 0.30 | = 7.16m <sup>3</sup> |
|                                   | 7x                            | 2.25     | x 1.10 | x 0.30 | = 5.20m <sup>3</sup> |
|                                   |                               |          |        |        | 12.36m <sup>3</sup>  |
| 2.                                |                               |          |        |        |                      |
| 2. making of barthen              |                               |          |        |        |                      |
| Shoulders -do-                    |                               |          |        |        |                      |
|                                   | 2x5                           | x 6.3    | 2x1.6  | 6 =    | 104.91m <sup>2</sup> |
|                                   | 2x8                           | x 5.9    | 7x 1.6 | 8 =    | 160.47m <sup>2</sup> |
|                                   |                               |          |        |        | 265.39m <sup>2</sup> |
| 3. patch repair on                |                               |          |        |        |                      |
| B.T -do-                          |                               |          |        |        |                      |
|                                   | 5x                            | 1.65     | x 1.3  | 0 =    | 10.73m <sup>2</sup>  |
| 4. Maint. of Slab                 |                               |          |        |        |                      |
| culvert -do-                      |                               |          |        |        |                      |
|                                   |                               |          |        |        | = 2 NO.              |
| 5. Maint. of Road                 |                               |          |        |        |                      |
| signs -do-                        |                               |          |        |        | = 0.44km.            |

Continuation

| Particulars                | Details of actual measurement |      |     |      | Contents of area |
|----------------------------|-------------------------------|------|-----|------|------------------|
|                            | No.                           | L.   | B.  | D.   |                  |
| 228.00m <sup>2</sup>       | Vide                          | T.m. | B p | (53) |                  |
| @ RS. 2.33/m <sup>2</sup>  |                               |      |     | RS.  | 531.00           |
| (8/11). Maint. of trees by |                               |      |     |      |                  |
| road side — do —           |                               |      |     |      |                  |
| 24 NO. Vide T.m. B p       |                               |      |     | (53) |                  |
| @ RS. 690.40/each          |                               |      |     | RS.  | 16570.00         |
|                            |                               |      |     | RS.  | 47066.00         |
| Add GST 12%                |                               |      |     | RS.  | 5648.00          |
| Add L. cost 1%             |                               |      |     | RS.  | 471.00           |
|                            |                               |      |     | RS.  | 53185.00         |
| Less 0.05% below           |                               |      |     | RS.  | 27.00            |
|                            |                               |      |     | RS.  | 53158.00         |

By  
20/09/24  
JR

By  
20/09/24  
JR

Material Statement

Gravel work - 12.36m<sup>3</sup>

By  
20/09/24  
JR