

2nd Year Maintenance

20

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Name of work- Maintenance of road from Jogi NH-28 Jogi Jawah					
Baba to Seh Tola under 111054					
Agency- M/s K.P. Constn Company					
Agreement No- 115301 2019-20					
Date of Start- 12/07/2019					
Date of Completion- 11/07/2020					
Actual date of comp- 23/03/2022					
2nd Year Maintenance 23/03/2021					
Period 23/03/2021					
① Restoration of Pavements					
1x 9.50 x 1.25 x 0.25 = 2.97m ³					
1x 7.50 x 1.10 x 0.30 = 2.47m ³					

1 X 8.50 X 1.20 X 0.30 = 3.06m ³
2 X 10.40 X 1.20 X 0.30 = 7.20m ³
1 X 8.15 X 1.15 X 0.25 = 2.34m ³
2 X 9.40 X 1.25 X 0.25 = 5.62m ³
1 X 6.15 X 0.90 X 0.30 = 1.66m ³
2 X 8.40 X 1.28 X 0.30 = 6.14m ³
2 X 10.40 X 1.20 X 0.30 = 7.20m ³
2 X 7.40 X 1.25 X 0.25 = 4.37m ³
1 X 9.50 X 1.10 X 0.25 = 2.61m ³
2 X 8.50 X 1.20 X 0.30 = 6.12m ³
2 X 7.40 X 1.10 X 0.25 = 3.85m ³
2 X 10.40 X 1.20 X 0.30 = 7.20m ³
2 X 9.40 X 1.28 X 0.30 = 6.91m ³
1 X 7.15 X 1.20 X 0.30 = 2.57m ³

Continuation

72.29m³

Abstract of cost

24

Sch. XLV—Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① Restoration of Rain cects					
Q-VTNB/20(1) =	72.29m ²				
P22(4) =	89.13m ²				
	161.42m ²				
e h. 378.32/m ² - h -	61068=				
② Maintenance of earthen Shoulder					
Q-VTNB/21(2) =	772.10m ²				
e h. 57.35/m ² - h -	44280=				
③ Maintenance of bitumen Surface road Repair to Pot holes					
Q-VTNB/22(3) =	85.72m ²				
e h. 294=00/m ² h -	25202=				
④ Maintenance of H.P. culvert					
Q-VTNB/23(5) =	61 Nos				
e h. 1109.67/each h -	66587=				
⑤ cutting of branches of trees					
Q-VTNB/23(6) =	16 Nos				
e h. 105.39/each h -	1686=				
⑥ cutting of shrubs					
Q-VTNB/23(6) =	33 Nos				
e h. 6.47/each h -	214=				
⑦ Trimming of grass					
Q-VTNB/23(7) =	1345.20m ²				

Continuation

139108=

Continuation