

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Akhilesh Kumar (Executive Engineer Gogri)	
Name of Block/Road :- Block- Simri Bakhtiyarpur	
Name of Road :- Khap Tola to chikania	
A. For Road	
1. Damage Location/Chainage :- 2515 m	
2. Damage Length :- 185 m	
3. Nature of Damage (Length Wise)	(i) Breach :- 195.00 m
	(ii) Crust Damage :- 0.00 m
	(iii) Only Flank Damage :- 0.00 m
whether traffic fully/Partialiy obstructed :- fully obstructed	
4. Details of Restoration :-	
(i) Material Being Used in Restoration :- Brick Bat	
(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB Machine, Roller	
(iii) Restored Length	In open Area :- 195.00 m
	In habitation Area :- 0.00 m
(iv) If Restoration work done in habitation Area give Reason :- N/A	
B. For Bridge (Size of Bridge/Culvert) N/A	
(1) Damage Location/Chainage :- N/A	
(2) No. of Span Damage :- N/A	
(3) Length of Span :- N/A	
(4) Nature of Damage (Pier/Abuttment/ Wing Wall/Approach Road Damage) :- N/A	
(5) Details of Restoration :- N/A	
(i) Material Being Used in Restoration :- N/A	
(ii) Equipment/Tools Being Used in Restoration Works :- N/A	
(iii) Restored Length :- N/A	
Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory	

A. Kumar
Signature of Inspector
(Official Seal)
R.W.D. Works Div.
Gogri

A. Kumar

मुख्य अभियंता-2 का कार्यालय
ग्रामीण कार्य विभाग, पटना।

पत्रांक- 471/330
प्रेषक,

/पटना, दिनांक- 03.02.24

ई0 श्रीप्रकाश,
मुख्य अभियंता-2
सेवा में,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिमरी बख्तियारपुर।

विषय: कार्य प्रमंडल, सिमरी बख्तियारपुर के अधीन FDR अंतर्गत वर्ष 2023 में आई बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ का अस्थायी पुनर्स्थापन कार्य हेतु तकनीकी स्वीकृति के संबंध में।

प्रसंग-आपका पत्रांक-86 अनु0, दिनांक 15.01.2024

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र द्वारा कार्य प्रमंडल, सिमरी बख्तियारपुर के अधीन FDR अंतर्गत वर्ष 2023 में आई बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ का अस्थायी पुनर्स्थापन कार्य का डी0पी0आर0 घटनोत्तर (Post Facto) तकनीकी स्वीकृति हेतु प्राप्त हुआ है, जिसकी विवरणी निम्नवत् है:-

Sl no.	Name of Scheme	Damaged Length (in k.m)	Amount
1	2	3	4
1	X Road L071 to Ramagar	0.130	43.451
2	Khap Tola to Chikania	0.195	81.102
3	Lagma Panchayat Sima se Khojraha Path	0.198	52.838
4	X Road L086 to Kanariya	0.066	23.019
5	L071-T03 to Khara Mushari	0.020	7.642
6	Dhanpura Panchayat ke Kabaiya to Nepal Road	0.192	24.410
7	Ghoghsam Koshi Bandh Nadi ke Kinare to Paschim Tola	0.124	40.297
8	Belbara Nepal to Hasuliya	0.049	23.883
	Total=	0.974	296.642

उक्त कार्य के प्राक्कलन पर घटनोत्तर (Post Facto) तकनीकी स्वीकृति प्रदान कर आवश्यक अग्रेतर कार्रवाई हेतु लौटाया जा रहा है।

अनु0-यथोक्त।

विश्वासभाजन

मुख्य अभियंता-2

Details of T.S
X

For Temporary Restoration Work - ₹8110253.99

Total Rs. = ₹8110253.99

Inspection has been done by E.E, R.W.D, Gogri on 12/01/2024.

Post facto Technically sanctioned for Rs. 8.110253.99/- (Eighty one Lacs Ten thousand two hundred fifty four rupees only) for temporary Restoration Work. Technical sanction is being accorded in expectation to Administrative Approval by Department.



Chief Engineer-2
Rural Works Department
Patna
03/01/24