

INSPECTION REPORT FOR MOTORABLE WORK

Name of PIUs :- Akhilesh Kumar (Executive Engineer Gogri)
Name of Block/Road :- Block - Sonbarsa
Name of Road :- Lagma Panchayat Sima Se Khojraha Path

A. For Road

1. Damage Location/Chainage :- 100.00m, 200.00m, 300.00m, 340.00m, 385.00m

2. Damage Length :- 198.00 m

3. Nature of Damage (Length Wise)	(i) Breach :-	198.00 m
	(ii) Crust Damage :-	0.00m
	(iii) Only Flank Damage :-	0.00m

whether traffic fully/Partially obstructed :- fully obstructed

4. Details of Restoration :-

(i) Material Being Used in Restoration :- Brick Bat

(ii) Equipment/Tools Being Used in Restoration Works :- Tractor, JCB Machine, Roller

(iii) Restored Length	In open Area :-	198.00 m
	In habitation Area :-	0.00m

(iv) If Restoration work done in habitation Area give Reason :- N/A

B. For Bridge (Size of Bridge/Culvert) N/A

(1) Damage Location/Chainage :- N/A

(2) No. of Span Damage :- N/A

(3) Length of Span :- N/A

(4) Nature of Damage (Pier/Abutment/
Wing Wall/Approach Road Damage) :- N/A

(5) Details of Restoration :-

(i) Material Being Used in Restoration :- N/A

(ii) Equipment/Tools Being Used in Restoration Works :- N/A

(iii) Restored Length :- N/A

Overall Grade of Restoration work (Satisfactory/Unsatisfactory) :- Satisfactory

A. Kumar

Signature of Inspector
Executive Engineer
(Official Seal)
Gogri

मुख्य अभियंता-2 का कार्यालय
ग्रामीण कार्य विभाग, पटना।

पत्रांक- 471/230
प्रेषक,

/पटना, दिनांक- 03.02.24

ई0 श्रीप्रकाश,
मुख्य अभियंता-2
सेवा में,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग, कार्य प्रमंडल, सिमरी बख्तियारपुर।

विषय: कार्य प्रमंडल, सिमरी बख्तियारपुर के अधीन FDR अंतर्गत वर्ष 2023 में आई बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ का अस्थायी पुनर्स्थापन कार्य हेतु तकनीकी स्वीकृति के संबंध में।

प्रसंग-आपका पत्रांक-86 अनु0, दिनांक 15.01.2024

महाशय,

उपर्युक्त विषयक प्रासंगिक पत्र द्वारा कार्य प्रमंडल, सिमरी बख्तियारपुर के अधीन FDR अंतर्गत वर्ष 2023 में आई बाढ़/अतिवृष्टि से क्षतिग्रस्त पथ का अस्थायी पुनर्स्थापन कार्य का डी0पी0आर0 घटनोत्तर (Post Facto) तकनीकी स्वीकृति हेतु प्राप्त हुआ है, जिसकी विवरणी निम्नवत् है:-

sl no.	Name of Scheme	Damaged Length (in k.m)	Amount
1	2	3	4
1	X Road L071 to Ramagar	0.130	43.451
2	Khap Tola to Chikania	0.195	81.102
3	Lagma Panchayat Sima se Khojraha Path	0.198	52.838
4	X Road L086 to Kanariya	0.066	23.019
5	L071-T03 to Khara Mushari	0.020	7.642
6	Dhanpura Panchayat ke Kabaiya to Nepal Road	0.192	24.410
7	Ghoghsam Koshi Bandh Nadi ke Kinare to Paschim Tola	0.124	40.297
8	Belbara Nepal to Hasuliya	0.049	23.883
	Total=	0.974	296.642

उक्त कार्य के प्राक्कलन पर घटनोत्तर (Post Facto) तकनीकी स्वीकृति प्रदान कर आवश्यक अग्रेतर कार्रवाई हेतु लौटाया जा रहा है।
अनु0-यथोक्त।

विश्वासभाजन

मुख्य अभियंता-2


Details of T.S

For Temporary Restoration Work = Rs. 52.83806 Lacs
Total Rs. = ₹ 52.83806 Lacs

Inspection has been done by E.E, R.W.D, Gogri on 12/01/2024.

Post facto Technically sanctioned for Rs. 52.83806 Lacs (Fifty two lacs eighty three thousand eight hundred six rupees only)

for temporary Restoration work. Technical sanction is being accorded in expectation to Administrative Approval by Department


Chief Engineer-2
Rural Works Department
Patna
03/02/24