



Home || MasterDataEntry || Existing Road || Core Network || Proposal || NIT || Agreement ||
 Execution || Quality Monitoring || Maintenance || General || Facility || Report ||
 Maintenance Reports || Data Verification || RSA || PMIS || Contractor Grievance || PMIS Reports ||
 GPS VTS ||

3rd Tier

2nd Tier

1st Tier

Inspection Details

Schedule Details

ATR Details

Maintenance ATR

3rd Tier Quality Monitoring

Inspection List

Inspection Details

Observation No.

:

518576

Monitor

Singh Devendra

State

Bihar

District

Samastipur

Road Name

MRL15-khari se dinmanpur via khairaj

Sanction Year

2022-2023

Package

BR30P3R13

Length (Km.)

5.45

Road Status

In Progress

Completion Date

--

Inspection Date

25-Jan-2024

Start Chainage (Km.)

0.45

End Chainage (Km.)

5.45

Sr.No. Item Description

Grade

Remarks

1

Quality Arrangements

Satisfactory

-

1. Quality Arrangements

Satisfactory

-

2

Attention To Quality

Unsatisfactory

-

1. Maintenance of QC Registers

Satisfactory

-

2. Verification of test results

Unsatisfactory

wbm III 1st layer failed in gradation at ch 2.4

3

Geometrics

Satisfactory

-

1. Road Way Width

Satisfactory

-

2. Carriage Way Width

Satisfactory

-

3. Camber

Satisfactory

-

4. Super elevation

Not Applicable

-

5. Extra Widening at Curves

Not Applicable

-

6. Longitudinal Gradient in case of road in hilly/ rolling terrain.

Not Applicable

-

4

Earthwork and Sub-grade

Not Applicable

-

Message's

State : Bihar | District : Samastipur
| Department : DPIU Of Samastipur
GEO PMGSY App

Node
II

Email -
ommashep2023@gmail.com
| Phone - 020-25503201

User
Manual

Eform
User
manual

Eform
PPT

© 2014
NRRDA. All
rights
reserved.

