

**कार्यपालक अभियंता का कार्यालय,
ग्रामीण कार्य विभाग, कार्य प्रमण्डल, झाझा।**

पत्रांक 1538 (3170)

झाझा

दिनांक 25/11/23 ।

प्रेषक,

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल— झाझा।

सेवा में,

नोडल पदाधिकारी
नई अनुरक्षण नीति 2018(MR 3054)
ग्रामीण कार्य विभाग, बिहार पटना।

विषय:— शीर्ष नई अनुरक्षण नीति 2018(MR 3054) अंतर्गत अनुरक्षण मद में राशि की अधियाचना के संबंध में।


महाशय ,

उपर्युक्त विषय के संबंध में कहना है कि शीर्ष नई अनुरक्षण नीति 2018 (MR 3054) अंतर्गत अनुरक्षण मद में कार्य की अद्यतन स्थिति के अनुसार अधियाचना वाछित प्रपत्र में तैयार कर आवश्यक कार्रवाई हेतु समर्पित की जाती है।

अतः अनुरोध है कि आवंटन विमुक्त करने की कृपा की जाय ताकि संवेदक को ससमय भुगतान की जा सके।

अनु०:—यथोक्त।

विश्वास भाजन


25.11.23

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमण्डल झाझा।

25/11/23

STANDARD FORMAT FOR ROADS QUARTERLY STATEMENT (Qtr-01)

1	Name of the Road	Madhua to Sahiya Road.		
2	Batch No.	RM/JA/JHA/19/0025		
3	Project ID	20804104025		
4	Total Length of Road (in Km)	5.200		
5	Length of Road to Meet Required Service Level [Completed length] (in Km) (1)	5.200		
6	No. of Total Quarter (ie 3 Months as a unit) in 5 years	20		
7	Ordinary Maintenance Cost as per Schedule (Agreement Amount for Maintenance) (in Lakh)	44.85802		
8	Quarterly Payment : 1/20 of Ordinary Maintenance Cost as per Schedule (in Lakh) (2)	2.24290		
Compliance Criteria	Standard Job Description	Non-Compliant		Reduction Payment (6) = (3) / (1) * (2) * (4)
		Length Non Compliant (3)	Weighted Value for Payment Reduction (%) (4)	
I	PAVED ROADS (CARRIAGEWAY)	0	60%	0.00000
II	SHOULDERS AND EMBANMENTS	0	10%	0.00000
III	CROSS DRAINAGE INCLUDING CULVERTS AND BRIDGES	0	15%	0.00000
IV	SIGNAGE AND ROAD SAFETY	0	10%	0.00000
V	VEGATAION		5%	0.00000
TOTAL PAYMENT REDUCTION FOR THE QUARTER (in Lakh) [5]				0.00000
TO BE PAID FOR THE QUARTER/DEMAND (in Lakh) [6]				2.24290

Date of inspection by E/I or his agent Prepared by
Contractor's self Control unit

Date

Signature of person inspecting road

Name and Designation of person inspecting road
(Signature)


25/11/23
Executive Engineer
Rural Works Department
Works Division, Jhajha

quisition Format for Scheme Head - MR (3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

Jhajha Qtr (01)

Name of Works Division :- Sonpur

Government of Bihar

OM01

Rural works Department

SUMMARY OF ORDINARY MAINTENANCE INSPECTION REPORT

To: Executive Engineer
RWD Works Division Jhajha

Date: 25.11.2023

Road From- Madhua to Sahiya Road.

Length of Road: 5.20 KM

Period : From 29.07.2021 To 28.10.2021

Inspector: J.E RWD Sub Division, Jhajha

Position: J.E

Standard Work item			Work	Units of work required in each kilometre										Comments
S No	Name	Units	1	2	3	4	5	6	7	8	9	10		
OM100 Sealed Pavement														
OM101	Pothole Patching	m ²	No	No	No	No	No	No					No. Pothole found.	
OM102	Surface Depression and Rut Patching	m ²	No	No	No	No	No	No					No Surface Depression and Rut Patching found	
OM103	Crack Sealing	Lm	No	No	No	No	No	No					No Crack Sealing found	
OM104	Surface Treatment												No Loss of Aggregate (Surface Ravelling) found	
	(a) Loss of Aggregate (Surface Ravelling)	m ²	No	No	No	No	No	No					No Bleeding/Flushing Required	
	(b) Bleeding/Flushing	m ²	No	No	No	No	No	No					No Crocodile Cracking found	
	(c) Crocodile Cracking	m ²	No	No	No	No	No	No					No Edge Repair Required	
OM105	Edge Repair	m ²	No	No	No	No	No	No					No Concrete Pavement Repair Required	
OM106	Digouts	m ²												
OM107	Concrete Pavement	m ³	No	No	No	No	No	No						
OM200	Other activities	Lm												
	Shoulder													
	Unsealed Shoulder	No											No Edge Drop off Required	
	(a) Edge Drop off	Lm	No	No	No	No	No	No					required	
OM201	(b) Roughness, Scouring or Potholes	Lm											No Holding water found	
	(c) Holding Water	Lm	No	No	No	No	No	No					No Embankment Repair Required	
OM202	Embankment Repair	No	No	No	No	No	No	No					Defects rectified within stipulated time.	
	Other Activitie (Raincut)													
OM 300 Drainage including culverts major														
OM301	Surface Drains & Verge	Lm	Yes	Yes	Yes	Yes	Yes	Yes					No Required	
OM302	Culvert Cleaning	Lm	Yes	Yes	Yes	Yes	Yes	Yes					Culvert maintain within stipulated time	
OM303	Culvert and Pit repair	m ²	Yes	Yes	Yes	Yes	Yes	Yes					No Required	

Name of Road-Madhua to Sahiya Road.

Name of Agency-Rajeev Kumar

$$Y = 0 \cdot X^2 + 0.828 \cdot X + 341.6$$

$$X = 0$$

$$Y = 341$$

(R) RURAL ROAD

Good Average Poor
<4000 4001-5000 >5001

Date	Time	Section	Length	Bumps	Speed	OR	IRI	CATEGOR Y	Latitude	Longitude	Event
		No.	in km	in mm	Rate	mm/km	mm/km	ROAD			
21/11/23	16:4:0	28	0.1	340	10.1	3400	3156	G	24.8672	86.508147	Normal
21/11/23	16:4:12	28	0.1	370	10.1	3700	3405	G	24.86806	86.50848	Normal
21/11/23	16:4:34	28	0.1	360	20.2	3600	3322	G	24.86893	86.508568	Normal
21/11/23	16:5:9	28	0.1	370	20.2	3700	3405	G	24.86986	86.508602	Normal
21/11/23	16:5:9	28	0.1	340	10.1	3400	3156	G	24.87076	86.508535	Normal
21/11/23	16:6:0	28	0.1	310	20.2	3100	2908	G	24.87165	86.508298	Normal
21/11/23	16:6:20	28	0.1	310	10.1	3100	2908	G	24.87255	86.508232	Normal
21/11/23	16:7:0	28	0.1	320	10.1	3200	2991	G	24.87345	86.508248	Normal
21/11/23	16:7:31	28	0.1	430	10.1	4300	3901	G	24.87429	86.50837	Speed Breaker
21/11/23	16:8:6	28	0.1	360	10.1	3600	3322	G	24.87524	86.508585	Normal
21/11/23	16:9:0	28	0.1	310	20.2	3100	2908	G	24.87589	86.509242	Normal
21/11/23	16:9:15	28	0.1	210	20.2	2100	2080	G	24.87666	86.50904	Normal
21/11/23	16:9:27	28	0.1	390	20.2	3900	3570	G	24.87708	86.508147	Normal
21/11/23	16:10:0	28	0.1	360	10.1	3600	3322	G	24.87768	86.507423	Normal
21/11/23	16:10:26	28	0.1	350	20.2	3500	3239	G	24.87772	86.50631	Normal
21/11/23	16:11:1	28	0.1	360	20.2	3600	3322	G	24.87821	86.50551	Normal
21/11/23	16:11:36	28	0.1	400	20.2	4000	3653	G	24.87891	86.50492	Normal
21/11/23	16:12:12	28	0.1	390	20.2	3900	3570	G	24.88108	86.50014	Normal
21/11/23	16:12:12	28	0.1	370	20.2	3700	3405	G	24.88252	86.500524	Normal
21/11/23	16:12:47	28	0.1	350	20.2	3500	3239	G	24.88419	86.500765	Normal
21/11/23	16:13:22	28	0.1	370	10.1	3700	3405	G	24.88489	86.501088	Normal
21/11/23	16:13:25	28	0.1	390	10.1	3900	3570	G	24.88565	86.50129	Normal
21/11/23	16:14:0	28	0.1	250	10.1	2500	2411	G	24.89163	86.498215	Normal
21/11/23	16:14:33	28	0.1	360	10.1	3600	3322	G	24.89196	86.49739	Normal
21/11/23	16:15:8	28	0.1	420	10.1	4200	3819	G	24.89207	86.49538	Speed Breaker
21/11/23	16:16:0	28	0.1	400	10.1	4000	3653	G	24.89163	86.1627	Normal

21/11/23	16:16:19	28	0.1	410	10.1	4100	3736	G	24.89199	86.49316	Normal
21/11/23	16:17:0	28	0.1	340	10.1	3400	3156	G	24.89184	86.491403	Normal
21/11/23	16:18:10	28	0.1	330	10.1	3300	3073	G	24.89166	86.490622	Normal
21/11/23	16:18:5	28	0.1	390	20.2	3900	3570	G	24.89115	86.489848	Normal
21/11/23	16:18:40	28	0.1	350	10.1	3500	3239	G	24.89089	86.489545	Normal
21/11/23	16:18:43	28	0.1	340	20.2	3400	3156	G	24.89095	86.488671	Normal
21/11/23	16:19:15	28	0.1	330	20.2	3300	3073	G	24.89117	86.48643	Normal
21/11/23	16:19:15	28	0.1	360	20.2	3600	3322	G	24.89112	86.485437	Normal
21/11/23	16:19:50	28	0.1	100	20.2	4000	3653	G	24.89124	86.486778	Normal
21/11/23	16:20:0	28	0.1	340	0	3400	3156	G	24.89104	86.485959	Normal
21/11/23	16:20:26	28	0.1	380	20.2	3800	3487	G	24.8911	86.485356	Normal
21/11/23	16:21:1	28	0.1	360	10.1	3600	3322	G	24.89126	86.484656	Normal
21/11/23	16:21:36	28	0.1	330	10.1	3300	3073	G	24.8913	86.484108	Normal
21/11/23	16:22:0	28	0.1	360	20.2	3600	3322	G	24.8914	86.482601	Normal
21/11/23	16:22:12	28	0.1	400	10.1	4000	3653	G	24.89151	86.48293	Normal
21/11/23	16:23:0	28	0.1	410	10.1	4100	3736	G	24.89153	86.48191	Normal
21/11/23	16:23:22	28	0.1	410	10.1	4100	3736	G	24.89211	86.4801	Normal
21/11/23	16:24:0	28	0.1	300	10.1	3000	2825	G	24.89299	86.48021	Normal
21/11/23	16:24:0	28	0.1	390	20.2	3900	3570	G	24.89365	86.48153	Normal
21/11/23	16:24:33	28	0.1	350	10.1	3500	3239	G	24.89438	86.48432	Normal
21/11/23	16:25:8	28	0.1	340	20.2	3400	3156	G	24.89512	86.48538	Normal
21/11/23	16:25:43	28	0.1	330	20.2	3300	3073	G	24.89623	86.48638	Normal
21/11/23	16:26:15	28	0.1	350	20.2	3500	3239	G	24.89798	86.48712	Normal
21/11/23	16:26:51	28	0.1	410	20.2	4100	3736	G	24.89891	86.48891	Normal
21/11/23	16:27:0	28	0.1	360	20.2	3600	3322	G	24.89901	86.48982	Normal
21/11/23	16:27:27	28	0.1	370	20.2	3700	3405	G	24.89998	86.48999	Normal
							Total				
							3308				