

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल- बक्सर

पत्रांक- 88 /बक्सर

दिनांक- 19/01/24

प्रेषक,

कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल- बक्सर

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी-सह-सचिव
बिहार ग्रामीण पथ विकास अभिकरण (BRRDA)
बुद्ध मार्ग, पटना।

विषय- शीर्ष 3054 (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) योजना अंतर्गत राशि की अधियाचना के सम्बन्ध में।

महाशय,

उपर्युक्त विषय के सम्बन्ध में कहना है कि योजना शीर्ष 3054 मरम्मत (बिहार ग्रामीण पथ अनुरक्षण नीति- 2018) अंतर्गत कराये गए कार्यों के भुगतान हेतु राशि की आवश्यकता है जिसे अधियाचना प्रपत्र के साथ सलंग्न कर भेजा जा रहा है।

अतः श्रीमान से अनुरोध है कि सलंग्न विवरणी के अनुसार आवंटन उपलब्ध कराने की कृपा की जाए ताकि संवेदकों द्वारा कराये गए कार्य का भुगतान किया जा सके।

अनु०- यथोक्त

विश्वासभाजन


19.01.24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

AK
19/01/24

FORM GFR 19-A
(SEE Government of India's Decision (I) below Rule-150)
Form of Utilisation Certificate upto the month of Jan 2024

MR (3054) New Maintenance Policy 2018

PIU - RWD (W), Div.- Buxar

Sl. No.	Name of Scheme	Sanction No. & Date with Amount (in Rs. Lacs)	Amount Received (in Rs. Lacs)	Particulars
1	Construction of Rural Roads under MR (3054) Maintenance	Lt. No.- 168, dt.-16/12/2023	10263.43060	Certified that out of Rs. 10263.43060acs received during the years in favour of Ex. Engineer, RWD (W), Div.- Buxar Bihar, a sum of Rs 10252.11790 lacs has been utilized for the purpose of MR (3054) New Maintenance Policy 2018 Schemes as given in the margin for which it was sanctioned and that the balance of Rs11.31270 lacs remaining unutilized at the end of the period under.
Total -				


- 2 Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled/ are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for which it was sanctioned.

Kind of Checks exercised :-

- Works have been supervised by Executive Engineer/ Supertending Engineer.
- Periodical inspection has been conducted by Executive Engineer/ Supertending Engineer.
- Construction materials have been tested
- Measurements have been recorded in the MBs and test check conducted by the Assistant.
- All other codal formalities have been observed.

3 Physical Progress achieved :-

- Construction of Road works
- Construction of CD works


Executive Engineer

R.W.D. (w) Div. Buxar


19/01/24

Acquisition Format for Scheme Head- MR (3054) under Bihar Rural Road Maintenance Policy- 2018 (Initial Rectification and Surface Renewal)

Name of Works Division- RWD, Works Division- Buxar

Sl No	Package No.	Name of Road	Project ID as per MIS	Administrative Approval (AA) Letter No. & Date	Administrative Approval (AA)		Agreement Amount (In Lakh)		Agreement No. & Date	Date Of Completion as per Agreement	Value of IRI (in mm/km)	Thickness of Bitumen Layer (in mm)	Value of Bitumen Content in percentage	Previous Total Allotted Amount (In Lakh)	Up-to-date expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
					Length (In Km)	Amount (In Lakh)	Initial Rectification With Surface Renewal (In Lakh)	5 Years Routine Maintenance (In Lakh)									
3	RM/BU/BU X/22/0013	L050-BUXAR DINARA ROAD TO KATHIRAI HOTE HUYE CHAKIA TAK (VR50)	10401902118	Letter No 1486 & 8/09/2022	3.00	143.711	80.45376	27.4365	04/MBD/2023-24 & dt19.05.2023	18.02.2024	2481	25 mm	5.00%	0	0	75.23697	

1. Signed Hard Copy and Soft Copy (in excel) of recorded IRI is enclosed
2. Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer
RWD (W), Div.- Buxar


AK
19/04/24

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, बक्सर


का0आ0स...85..... बक्सर/ दिनांक...19/01/24

कार्यालय आदेश

प्रमाणित किया जाता है कि बिहार ग्रामीण पथ अनुरक्षण नीती-2018 योजनान्तर्गत L050-BUXAR DINARA ROAD TO KATHRAI HOTE HUYE CHAKIA TAK (VR50) पथ का कार्य गुणवत्ता एवं विशिष्टियों के अनुरूप पूर्ण कराया गया है। पथ के मापीपुस्त की जाँच मेरे द्वारा 10 प्रतिशत, सहायक अभियंता द्वारा 50 प्रतिशत एवं कनीय अभियंता के द्वारा शतप्रतिशत किया गया है।



कनीय अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रशाखा राजपुर


19/01/2024
सहायक अभियंता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल राजपुर


19.01.24
कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, बक्सर

File :G:\MEMRAJ\060119111.xlsx Section No. :67. Egn :test

Name of Customer :Memraj Construction Pvt.Ltd, Name of Work/ Road :L050 Buxar Dinara road To Kathrai Hote hue



[Signature]
19/01/24
JE

[Signature]
19/01/2024
AE

[Signature]
19.01.24

Name of Road :-L050-BUXAR DINARA ROAD TO KATHRAI HOTE HUVE CHAKIA TAK (VR50) Contractor Name:-Mamerej Construction Privae Limited

Date	Time	Section	No.	Length	Bumps	Speed	OR	IRI\TEGORY	Latitude	ongitude	Event
6/1/24	16:32:0	67	0.1	200	10	2000	2490 G	25.35448	84.3015	Normal	$Y = 0 * X^2 + 0.816 * X + 249$
6/1/24	16:33:31	67	0.1	200	10	2300	2589 G	25.35416	84.3106	Normal	$X = 0$
6/1/24	16:34:6	67	0.1	200	10.1	2000	1880 G	25.35364	84.31598	Normal	$Y = 249$
6/1/24	16:34:41	67	0.1	250	10.1	2500	2288 G	25.35324	84.32222	Normal	
6/1/24	16:35:17	67	0.1	220	10.1	2200	2044 G	25.3532	84.33232	Normal	
6/1/24	16:35:52	67	0.1	240	10.1	2400	2207 G	25.35247	84.3348	Normal	(R) RURAL ROAD
6/1/24	16:36:0	67	0.1	260	10.1	2600	2370 G	25.35171	84.34007	Normal	Good
6/1/24	16:36:27	67	0.1	190	10.1	1900	1799 G	25.35085	84.33888	Normal	Average
6/1/24	16:36:27	67	0.1	250	20.2	2500	2288 G	25.35076	84.34797	Normal	Poor
6/1/24	16:37:2	67	0.1	220	20.2	2200	2044 G	25.35067	84.35757	Normal	<4000 4001-5000 >5001
6/1/24	16:37:2	67	0.1	280	20.2	2800	2533 G	25.35061	84.3672	Normal	
6/1/24	16:37:38	67	0.1	290	10.1	2900	2615 G	25.35056	84.37743	Normal	Machine ID=415
6/1/24	16:38:13	67	0.1	310	0	3100	2778 G	25.35023	84.38602	Normal	IRI Value=2481
6/1/24	16:39:0	67	0.1	300	0	3000	2696 G	25.35011	84.39562	Normal	
6/1/24	16:39:22	67	0.1	300	10.1	3000	2696 G	25.35006	84.40572	Normal	
6/1/24	16:40:0	67	0.1	300	10.1	3000	2696 G	25.3498	84.41582	Normal	
6/1/24	16:40:0	67	0.1	360	10.1	3600	3186 G	25.34962	84.42542	Normal	
6/1/24	16:40:33	67	0.1	330	10.1	3300	2941 G	25.34907	84.43163	Curve	
6/1/24	16:41:8	67	0.1	210	20.2	2100	1962 G	25.34817	84.43	Normal	
6/1/24	16:41:8	67	0.1	230	20.2	2300	2125 G	25.34731	84.43552	Normal	
6/1/24	16:41:8	67	0.1	180	20.2	1800	1717 G	25.34638	84.4377	Normal	
6/1/24	16:41:44	67	0.1	260	30.3	2600	2370 G	25.34552	84.43988	Normal	
6/1/24	16:42:0	67	0.1	240	30.3	2400	2207 G	25.3446	84.44242	Normal	
6/1/24	16:42:0	67	0.1	190	30.3	1900	1799 G	25.34381	84.44578	Normal	
6/1/24	16:42:19	67	0.1	190	30.3	1900	1799 G	25.34304	84.4513	Normal	
6/1/24	16:48:0	67	0.1	260	30.3	2300	2370 G	25.34929	84.4313	Normal	
6/1/24	16:48:12	67	0.1	260	10.1	2700	2890 G	25.34912	84.4409	Normal	
6/1/24	16:49:22	67	0.1	260	10.1	3200	3289 G	25.3486	84.44932	Normal	

19.1.24
JE

19/01/2024
AE

19.01.24