

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	

2nd year Maintenance

Name of work:- Rambar Sauna do
Malahi tola under MMGSY (Gen)

Authority - E.C. Road, Bagalpur.

Agency - Arbind Singh.

Agg No - 305 BD/2021-22

D/S - 03/07/2021

D/C - 01/08/22

A/D/C - 20/05/2022

Work Done:-

(C.I.) Restoration of Rain Cut

12 x 2.4 x 1.6 x 0.30 =	15.82 m ³
9 x 2.1 x 1.45 x 0.30 =	8.22 m ³
17 x 1.90 x 1.65 x 0.30 =	15.99 m ³
9 x 2.1 x 1.45 x 0.30 =	2.14 m ³
6 x 1.40 x 0.85 x 0.30 =	8.22 m ³
	48.39 m ³

(C.I.) Maint. of Earthen Shoulders:-
with soil.

15 x 4.30 x 1.10 =	70.95 m ²
12 x 3.95 x 1.10 =	52.14 m ²
8 x 4.65 x 1.10 =	40.92 m ²
17 x 5.55 x 1.10 =	103.785
19 x 5.55 x 1.10 =	116.00 m ²
Limit - 337.50	383.795

Continuation

Material statement.

e/wg -	105 m ³ -
--------	----------------------

Bitumen	64 kg
---------	-------

Chis -	2 m ³ -
--------	--------------------