

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
ON 3rd year maintenance Bill					
Name of work - S.O. 50 to Mullin Jala					
Name of Agency - Rakesh Kumar					
Agreement No - 91 SBD 2020-21					
Actual Date of completion - 16/5/21					
(11) Resurfacing of road works					
$6 \times 8.8 \times 0.65 \times 0.3 =$					10.296 m^3
$8 \times 8 \times 0.45 \times 0.30 =$					8.64 m^3
$7 \times 12.30 \times 0.7 \times 0.30 =$					18.081 m^3
$6 \times 10.10 \times 0.7 \times 0.30 =$					12.726 m^3
$10 \times 7.6 \times 0.5 \times 0.36 =$					11.40
$8 \times 8.8 \times 0.8 \times 0.30 =$					16.896 m^3
					$= 78.039$
(2/2) Maintenance of Ethen shoulder					
$4 \times 7.3 \times 0.8 =$					23.36 m^2
$5 \times 8.3 \times 0.7 =$					29.05 m^2
$6 \times 9.3 \times 0.70 =$					39.06 m^2
$7 \times 16.50 \times 0.90 =$					103.95 m^2
$8 \times 10.40 \times 0.70 =$					58.24 m^2
$5 \times 11.50 \times 0.60 =$					34.50 m^2
$4 \times 15.40 \times 0.8 =$					49.28 m^2
$5 \times 10.60 \times 0.6 =$					31.80 m^2
$6 \times 11.80 \times 0.8 =$					56.64 m^2
Total =					425.88 m^2
(3/5) Patch repair and road filled					
Pot holes with 75mm WBM					
Q2-3					

Continuation

Continuation