

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
First year Maintenance Bij					
N/W - Const. of Road From					
Malahi Dwarika Ray Ka					
ghar se dakshin to					
Nim Chak Balha.					
Agency - vikash Kumar Singh					
Agreement No - 3605BD/2021-22					
Date of Work order - 02.9.2021					
A. Date of Completion - 25.08.2022					
1 Restoration of main					
Cuts and berms of E/R					
$6 \times 7.8 \times .90 \times .30 =$					12.636 m ³
$7 \times 9.3 \times .95 \times .30 =$					18.55 m ³
$5 \times 7.35 \times .80 \times .30 =$					8.82 m ³
$8 \times 5.0 \times .80 \times .30 =$					9.60 "
$6 \times 9.3 \times .95 \times .30 =$					18.55 "
				C. of R =	68.156 m ³
				Lt =	63.74 m ³
2. making up berms and					
Shoulder of E/R					
$6 \times 7.5 \times .90 =$					40.50 mt
$4 \times 8.5 \times .90 =$					30.60 mt
$6 \times 10.5 \times .90 =$					56.70 mt
$8 \times 9.25 \times .95 =$					70.30 mt

Continuation

$$12 \times 9.65 \times .85 = 98.43 "$$

$$7 \times 9.35 \times .90 = 58.90 "$$

$$C. of R = 355.43 m^2$$

$$Lt. 354.09 m^2$$

Scanned with CamScanner