

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
① M/W - Raghapur naggy road side Rambhoreth Rai K. Ghatak					
② Agency - Vijay Kumar Ramtekar, Sadhana, Raghapur, Ramtekar					
③ Agn - naggy / S.D. - 69/2018-19					
work done					
① Rectification of sub cut					
23 x 4.15 x 0.90 x 0.45 = 28.65 m ³					
18 x 3.65 x 0.95 x 0.60 = 37.45 m ³					
10 x 3.85 x 0.85 x 0.30 = 9.82 m ³					
					85.92 m ³
② Maintenance of earthy - 8 km					
19 x 3.0 x 0.85 = 48.45 m ³					
					Limit 483.30 m ³
③ Pot holes repair					
1 x 5.95 x 3.20 = 19.04 m ³					
1 x 9.70 x 3.35 = 32.5 m ³					
1 x 8.70 x 2.95 = 25.67 m ³					
					77.21 m ³
④ Patch repair					
Area: 77.21 m ² (3)					77.21 m ²
⑤ Randomness of H/A/P -					1.0

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
9/13 Cutting of shrubs					
T.M.N. - P(13) -	13				
@ 6-60/each					86.40
10/14 Trimming of grass					
T.M.N. - P(13) -	178.5 m ²				
@ 2.20/m					393.70
					1,05,516.40
less 10% As per					10,552.20
					94,964.20
Plays					
04/10/24					
04/10/24					

Slam
04/10/24
04/10/24