

3rd Year Maintenance
ABSTRACT of work

28

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
(1) Restoration of runway aty for side P21 & 22 → 30.45m @ 380-581m					115942
(2) Making of Bays for side P22 & 23 → 169.31m @ 5838m					98832
(3) Repair to butts bay for side P22 & 23 → 30.23m @ 264.46m					79962
(4) Patch repair for side P22 & 23 → 30.23m @ 232.6m					7032
(5) Minton of 40 CD for side P22 & 23 → 1m @ 1117.00m					11170
(6) Minton of 2000 sq for side P22 & 23 → 0.06m @ 1074.50m					692
(7) Minton of 2000 sq for side P22 & 23 → 0.08m @ 573.96m					440
(8) Cutting of branches of tree in side P22 & 23 → 1m @ 106.52m					106
(9) Cutting of shrub → 5m @ 6.52m					33
(10) Trimming of grass → 2.4m @ 2.48m					57
(11) Painting of P22 & 23 for side P22 & 23 → 20.6m @ 108.98m					2249
(12) Repair of 56.0m @ 850.39m					73180

Continuation

M 113315
C 01



