

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Area of work 5 ges wint of room for kirpa bha to mahabhar					
Agency - Prakash Construction					
Ag. No - 35 SRS D/17-18					
Actual work of carpentry					11/3/19
(1) Restoration of rain water					
2 x 5 m x 30 m x 1.10 m to 3 m = 758.4					
2 x 6 m x 30 m x 1.10 m to 3 m = 118.8					
					Total 277.04
					Unit = 243.00
(2) Marking of earthwork shoulder					
20 m x 30 m x ? 25 m = 1360.0					
(3) Repair to pit holes					
10 x 6.612 m x 3.25 m = 255.40					
(4) pit holes					
Area Bm as 3 = 235.40					
(5) Patch repair					
Area Bm as 4 = 2255.40					
(6) Maintenance of P					
CD - 5 m					
(7) Maintenance of earth culvert - 4 m					
(8) Maintenance of road sup. - 3.04					
(9) Maintenance of 20 x 86 - 0.5704					
(10) (5) Cutting of formation - 10 m					
(6) Cutting of shoulder = 10 m x 3.25 = 32.0					
(55) Tring Continuation 10 x 6.7 m x 2.25					
(12) White wash 1516.25					
Grand total 45.00					
514/23					
Grand total 45.00					

