

5th year maintenance

86

Sch. XLV-Form No. 134

Particulars	Details of actual measurement				Contents of area
	No.	L.	B.	D.	
Road -	Karpabrigha to Mahabha				
Agency -	Prakash CapM				
of No -	35 SBD/12-18				
Actual Date of completion	11/3/19				
① Restoration of main culvert					
10 x 50 m x 1.10 m x 0.25 m = 16.5 m ³					
8 x 50 m x 1.10 m x 0.25 m = 132 m ³					
	Total = 297 m ³				
	Unit = 273 m ³				
② Making of fall pipe					
of 10 in shoulder					
10 x 62 cm x 2.25 m = 158 m ³					
③ Repair to pot holes					
10 m x 8.51 m x 3.25 m = 319.25 m ³					
④ Maintenance of ur & my					
about including poles & kelly					
4 surfaces					
Area same as item 3 = 319.25 m ³					
⑤ Patch repair on already filled pot holes					
Area same as item 4 = 319.25 m ³					
⑥ Maintenance of H.P. of					
= 5 m ³					
⑦ Maintenance of slab culvert					
4 m ³					
⑧ Maintenance road signs - 30/14					
⑨ Maintenance of road sign					
20.720 m ³					
⑩ Cutting of branches of tree					
18 m ³					
Continuation					
(i) Cutting of shrubs	32.500 m ³				
(ii) Trimming of grass	10 x 10 x 11.25 x 2.0				
white way	2531.25 m ³				
2574/24	2214 m ³				



Continuation