

कार्यपालक अभियंता का कार्यालय
ग्रामीण कार्य विभाग, कार्य प्रमंडल, समस्तीपुर
e-mail- eerwdsamastipur@gmail.com

पत्रांक 1463/23 दिनांक 6/7/24

प्रेषक:—

कार्यपालक अभियंता,
ग्रामीण कार्य विभाग,
कार्य प्रमंडल, समस्तीपुर।

सेवा में,

अपर मुख्य कार्यपालक पदाधिकारी—सह—सचिव
ग्रामीण कार्य विभाग, बिहार, पटना।

विषय:—

शीर्ष New Maintenance Policy 2018 मद में आवंटन उपलब्ध कराने के संबंध में।

महाशय,


उपर्युक्त विषयक शीर्ष New Maintenance Policy 2018 योजनान्तर्गत निर्मित/
निर्माणाधीन पथों का विहित प्रपत्र में अधियाचना पत्र संलग्न कर भेजा जा रहा है।

अतः अनुरोध है कि संलग्न अधियाचना पत्र के अनुसार आवंटन उपलब्ध कराने की कृपा

की जाय।

अनु०—यथोक्त।

विश्वासभाजन


कार्यपालक अभियंता
ग्रामीण कार्य विभाग
कार्य प्रमंडल, समस्तीपुर
6/7/24

FROM GFR 19-A

(See Government of India's Division (I) below Rule- 150)

Form of Utilization Certificate upto 02.07.2024

PIU- E.E., R.W.D. Works Division, Samastipur

S.N.	Name of Scheme	Sanction No.& Date	Amount Received	Particulars
1	Construction of Rural Road under New Maintenance Policy-2018	Secretary cum Empowered Officer BRRDA Bihar Patna vide upto Lt. n.-82, dt.28.06.2024	1167856945.00	Certified that out of Rs.1167856945.00 received upto 02.07.2024 in favour of Executive Engineer R.W.D. Works Division Samastipur a sum of Rs.1154086624.00 has been utilized for the purpose of New Maintenance Policy-2018 Schemes as given in the margine for which it was sanctioned and that the balance of Rs.13770321.00 remaining unutilized at the end of period under report.
			1,167,856,945.00	

2. Certified that I have satisfied myself that the conditions on which the grants-in-aid was sanctioned have been duly fulfilled are being fulfilled and that I have exercised the following checks to see that the money was actually utilized for the purpose for the which it was sanctioned.

Kind of Checks exercised:-

- i Works have been supervised by Executive/Superintending engineer.
- ii Periodical inspection has been conducted by Executive/Superintending engineer.
- iii Construction materials have been tested.
- iv Measurements have been recorded in the MB's and test check conducted by Assistant Engineer/Executive
- v All other codal formalities have been observed.

3 Physical Progress achieved:-

- i Construction of Road work.
- ii Construction of CD works.


Executive Engineer
 Works Division Samastipur
 Rural Works Dipartment

 04/07/24

Requisition Form for scheme Head : MR(3054) Under Bihar Rural Road Maintenance Policy-2018 (Initial Rectification and Surface Renewal)

RWD, Works Division : Samastipur																			
Sl No	Package No	Project ID as Per MIS	Name of Road	Administrative Approval		Administrative		Agreement Amount		Agreement No & Date	Date of Completion as per Agreement	Actual Date of Completion	Value of IRI (In mm.km)	Thickness of Bitumen Layer (In M/M)	Value of Bitumen Content in Percentage	Previous Total Allocated Amount (In Lakh)	Upto date Expenditure as per MIS (In Lakh)	Requisition against work done (In Lakh)	Remarks
				(AA) Letter No & Date		Length (Km)	Amount (In Lakh)	Initial Rectification with Surface Renewal	5 Year Routine Maintenance										
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	
1	RMTS/SAM/24/0009	32010102134	L022-L022A to Rajpoot Tola (TRAC022)	4742 & 04.09.2023	1.785	113.290	73.283	17.500	37(MBD)2023-24	01.12.2024	Complete	2997	25	5.0	0	0	27.000	Complete	
2		32010102199	L055-T03 Madarsa Chowk to Jamia Tola Salipur Baghaunt (VR55)																
Total																		77.000	

1 Signed Hard Copy and Soft Copy (In Excel) of recorded IRI is enclosed.

2 Up-to-date Physical Progress has been uploaded in MIS

Executive Engineer

RWD (W) Div. Samastipur

5/12/24

Name of Customer : Mursid Alam

Name of Work/ Road : L022A To Rajput Tola

Lab Job number : 33

Date : 01.07.2024

Section No. : 33

Test Date : 01.07.2024

Machine No : 338

Start S No :

Start E No :

Weather :

Start Location :

End Location :

Road Name : L022A To Rajput Tola

Road Type : (R) RURAL ROAD

Side :

UIV Range : 1858 To 4000

Dist Range : 0 To 1


Equation : $Y = 0 * X^2 + 1.136 * X + 132.5$

Interval : 1000 mm/km

Print Generate Report and Graph

Redraw Graph

Map View



01/07/24 01/07/24
ATM.

[Handwritten signature]

Name of Road :- L022A To Rajput Tola

Section no.-33

Date	Time	Section No.	Length in km	Bumps in mm	Speed Rate	OR mm/km	IRI mm/km	CATEGORY	Latitude	Longitude	Event
1/7/24	12:12:8	33	0.1	240	0	2400	2858	ROAD	25.87122	85.687484	Normal
1/7/24	12:12:41	33	0.1	250	10.1	2500	2972	G	25.87113	85.687675	Normal
1/7/24	12:13:19	33	0.1	260	10.1	2600	3086	G	25.87104	85.687707	Normal
1/7/24	12:13:53	33	0.1	250	10.1	2500	2972	G	25.870846	85.687857	Curve
1/7/24	12:14:10	33	0.1	240	10.1	2400	2858	G	25.870544	85.688185	Normal
1/7/24	12:14:44	33	0.1	260	10.1	2600	3086	G	25.870613	85.688769	Normal
1/7/24	12:15:12	33	0.1	250	10.1	2500	2972	G	25.869635	85.688821	Normal
1/7/24	12:15:54	33	0.1	280	10.1	2800	3313	G	25.869617	85.688935	Normal
1/7/24	12:16:11	33	0.1	240	10.1	2400	2858	G	25.869307	85.690072	Curve
Total =			0.900	Km	AVG. 2997.22						

[Signature]
01/07/24
JS

[Signature]
Executive Engineer
R.W.D.(W) Division,
Samastipur